

File Number:	9754	Arms Service number:	9716508
Last Name:	KRAMPER	First Name:	WILLIAM
Street:	5163 WINDLEIGH PLACE	City:	ST LOUIS
State:	MO	Zip:	63128
Home Ph:		Home Ph:	314 843 3192
Work Ph:		Product Type:	F F A T O
Type Concern:	S	PI PD P S C:	
Concern:	FIRED ON SAFE RELEASE		
Case Code:	4039	Quasi:	NO FAULT FOUND
Assigned To:	KAST	Classification:	UNC
Settlement Detail:	REPAIR N/C	Settlement Amount:	\$0.00
Date Opened Rem:	11/12/97	Date Opened by PS:	11/12/97
Date of Incident:		Date Closed:	11/12/97
Date to Analyze:		Date from Analysis:	
Model:	700	Serial:	S6271504
RAMAC:	700	Litigation:	
Cuspidy:		Comments:	
Time of Modification:	11:11:46 AM	Date of Modification:	11/12/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-19508

INITIAL
JJH

CUSTOMER ORDER NO.

ATTN JACK KAST

DATE RECEIVED

11/11/97

DATE OPENED

11/12/97

DATE CODE

XQ 12-94

SERIAL NUMBER

S6271504

NEW SERIAL NUMBER

MODEL AND GRADE

700 22-250

VSSF

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

KRAMPER, WILLIAM
5163 WINDLEIGH PLACE
ST LOUIS

MO 63128

KRAMPER, WILLIAM
5163 WINDLEIGH PLACE
ST LOUISMO
63128

CUST NO: 157779 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Fault on safe release

MAIN FAULT

*Unable to duplicate customer concern as rifle,
took trigger assy. apart and still no fault found.
Exchange trig assy at N/C to restore customer
confidence in the rifle.*

PARTS

COMMENTS

*Trig pull 3 1/4 LBS as reqd.
Seal engagement in spec.*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 7-97

PS 34695

5163 Windleigh Place
St. Louis, MO 63128
November 1, 1997

Mr. Jack Kast
Remington Arms
14 Hoefler Ave.
Ilion, NY 13357

Dear Jack,

Enclosed is a Remington 22/250 Model 700 varmint rifle. As we discussed, twice this rifle fired with a cartridge in the chamber when I moved the safety from the safe position to the fire position. I did not have my finger on the trigger. I would appreciate your help in correcting this problem. If you have any questions please feel free to call me at 314-843-3192.

Bill

William G. Kramper