

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

FIND

File Number: 9380 Arms Service number: 9707923

Last Name: LEGG, PA First Name: TRICKA

Street: 3137 S BEVERLY CIRCLE City: MESA

State: AZ Zip: 85210 Home Ph:

Work Ph: Product Type: F F A T O

Type Concern: S PI PD P S C Concern Code: 1008

Concern: FIRED ON BOLT CLOSING

Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS

Assigned To: KAST Classification: UNJ UNJ UNJ UNJ

Settlement Detail: REPAIR SPCL PRICE Settlement Amount: \$0.00

Date Opened Rem: 5/10/97 Date Opened by P/S: 5/21/97 Caliber: 280

Date of Incident: Date Closed: 5/21/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: 06859165 Date Code: PL Date Mfgd: 5/1/91

RAMAC: 700 Litigation: ☐ PreLitigation: ☐ Obsolete: ☐

Custody: Comments:

Time of Modification: 10:14:43 AM Date of Modification: 5/21/97

Could this case be in the first stages of litigation? (Y/N)

FLTR CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-07923

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
04/09/97

DATE OPENED
04/10/97

DATE CODE
PL 6-91

SERIAL NUMBER
C6659165

NEW SERIAL NUMBER

MODEL AND GRADE
700 280

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

LEGG, PATRICK A
3137 S BEVERLY CIRCLE
MESA

AZ 85210

SHIP TO:

LEGG, PATRICK A
3137 S BEVERLY CIRCLE
MESA

AZ

85210

CUST NO: 165443 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Prod Serv.

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Trigger pin rusty and trigger pounds pull and screw engagement screws altered from unsafe condition outside of the factory (Not recommended.)

Exchange trigger assy. at a special price strictly as a gesture of good will.

PARTS

trig. Assy

COMMENTS

This pull 1 3/4 to 2 1/4 LBS as Recd. no perceptible travel.

Pounds pull spring not fully returning trigger because of screw being backed out too far.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/96

Patrick A. Legg
3137 S. Beverly Cir.
Mesa, AZ. 85210-8202
Email: Patlegg@AOL.Com
April 2, 1997

Arms Service Div.
Remington Arms Co. Inc.
Illion, New York 13357

Dear Sirs:

I am sending you my Remington Model 700 BDL custom deluxe in 280 remington cal. serial number c6659165.

The rifle discharged in my garage when I chambered a live round to check my bullet seating depth. I was fortunate this time and there were no injuries only stained boxer shorts. I could not unlock the bolt initially but rather had to cam it further in the close direction before the spent casing could be removed. In the box is the spent casing.

The rifle has always been very reliable in the past five years since I've owned it. It probably has less than 500 rounds through it. Some additional history that may or may not be important. Two months ago while Pig hunting I carried the rifle with a live round in the chamber and the safety on. At the end of the day I tried to fire the rifle, but it misfired. It dented the primer but failed to fire, I rechambered the round and it fired successfully. I may well have a ammo problem but I would feel better if the rifle was checked out by factory service people.

If repairs are needed, press on and send me the bill at the above address.

Thank you very much for your time.

Patrick A. Legg