

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

File Number: 9162 Arms Service number: 9704244

Last Name: LYMBERRY First Name: JACK K

Street: 9110 HENDON LANE City: HOUSTON

State: TX Zip: 77036 Home Ph:

Work Ph: Product Type: F E A T O

Type Concern: S P I P D P S C Concern Code: 1008

Concern: FIRED ON BOLT CLOSING

Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS

Assigned To: SANITA Classification: UNJ UNJ UNC UND J

Settlement Detail: REPAIR AT SPEC PRICE Settlement Amount: \$0.00

Date Opened Rem: 2/17/97 Date Opened by P/S: 2/17/97 Caliber: 30-06

Date of Incident: Date Closed: 2/18/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: 357126 Date Code: FR Date Mfgd: 6/1/68

RAMAC: 700 Litigation: ☐ PreLitigation: ☐ Obsolete: ☐

Custody: Comments:

Time of Modification: 1:52:15 PM Date of Modification: 2/18/97

Model designation FLTR NUM

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORLER R 97-04244			
INITIAL JJM		CUSTOMER ORDER NO.		ATTN CHERYL STARING BOTTOM HALF OF MOUNTS ONLY					
DATE RECEIVED 02/11/97	DATE OPENED 02/17/97	DATE CODE PR 6-68	SERIAL NUMBER 357126	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06		BDL		
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT							
FROM: LYMBERRY, JACK K 9110 HENDON LANE HOUSTON TX 77036				SHIP TO: LYMBERRY, JACK K 9110 HENDON LANE HOUSTON TX 77036					
CUST NO: 162278 C.B.D.L.									
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		PROM. DATE		ESTIMATED	VIA UPS		
GUN CONDITION		<div style="border: 1px solid black; padding: 5px; margin: 0 auto; width: 80%;"> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED </div> <div style="width: 45%;"> REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL </div> </div> </div>							
CUSTOMER CONCERN		AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT		
CYCLE									
TRIGGER GROUP ✓									
BOLT ASSY.									
BARREL ASSY.									
REC. ASSY.									
WOOD				C1	C3				
METAL				C2					
MAIN FAULT									
<div style="font-family: cursive; font-size: 1.2em;"> <p>Upon receipt rifle was in operation, the bolt stop, which a door safety cam was seized up from being covered with a sticky gummy substance. Action also dirty. The sear has been removed from all 3 adjustment screws. Mfg. 1968.</p> <p>#26345</p> <p>1008 4206 4215</p> </div>									
ARTS				COMMENTS					
<div style="font-family: cursive; font-size: 1.2em;"> <p>Replace the complete Trigger Assm & Clean the Action at 1/2 the normal cost.</p> </div>				REPAIRMAN		CLEAN	TEST	TAX SET	PATTERN
				GALLERY TESTER		DATE	DATE	DATE	DATE

9110 Fendon Lane
Houston, TX 77036

REMINGTON ARMS

Ms. Cheryl Staring:

Am confirming our telephone conversation of January 30, 1997 regarding problems with my Remington Model 700 BDL Serial No. 357126 has given me on three (3) different occasions. I had attempted to fire it after moving the safety to fire with no response. I checked the chamber to see if shell was good and closed and behold it fired, I then ejected the shell and another shell was attempted and it too fired. Luckily, no one was hurt, I returned to the camp and again two (2) times the shell would fire when the bolt went forward. I had the rifle checked and cleaned. To my surprise, 4 weeks ago I went hunting and while in the deer stand, gun was loaded and could not put the safety on again. Shells were removed and bolt was actuated approximately 15 times before the safety was moveable. Evidently the firing pin (striker) is hanging up.

I appreciate your interest in correcting this problem.

Yours truly,

Jack K. Lymberry
Jack K. Lymberry