

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

derwick

File Number: 8904 Arms Service number: 9627183

Last Name: MICHENER First Name: MICHAEL

Street: 298 PLEASANT ST City: PERU

State: NY Zip: 12972 Home Ph:

Work Ph: Product Type: F F A T O

Type Concern: 5 PI PD P S C Concern Code: 1007

Concern: FIRED IN SAFE RELEASE

Cause Code: 4039 Cause: NO FAULT FOUND

Assigned To: KAST Classification: UNC UNJ UNC UND J

Settlement Detail: REPAIR AT SPCL PRICE Settlement Amount: \$0.00

Date Opened Rem: 12/12/96 Date Opened by P/S: 1/6/97 Caliber: 25-06

Date of Incident: Date Closed: 1/6/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: A6427973 Date Code: 40 Date Mfgd: 3/1/77

RAMAC: 700 Litigation: ☐ PreLitigation: ☐ Obsolete: ☐

Custody: Comments:

Time of Modification: 7:21:16 AM Date of Modification: 1/7/97

Additional info.

FLTR

NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 96-27183INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
12/05/96DATE OPENED
12/12/96DATE CODE
AO 3-77SERIAL NUMBER
A6427973

NEW SERIAL NUMBER

MODEL AND GRADE
700 25-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

MICHENER, MICHAEL
298 PLEASANT ST
PERU

NY 12972

SHIP TO:

MICHENER, MICHAEL
298 PLEASANT ST
PERUNY
12972

CUST NO: 157286 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

*Some rust on connector - appears that
trig Assy has been recently oiled*

REPAIR CHARGE *38.00*

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL *38.00*

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D1	E4	F4
WOOD			C1	D2	E5	F5
METAL			C2	D3		

MAIN FAULT

*Unable to duplicate customer concern as rec'd. Took trig.
assy. apart and no fault found. Exchange trig. assy.
at a special price to restore customer's confidence
in the rifle.*

PARTS

*Trig Assy
old style*

COMMENTS

*trig pull. 4'1/4 to 4'1/2 LBS as
rec'd.*

Firing pin rusted as rec'd.

Sear engagement OK

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 6/96

PS 34755

Remington Arms.

When This Gun Was 2 Years Old, About 1977 or 1978,
IT FIRED WHEN THE SAFETY WAS MOVED FROM "S" TO "F".
I ATTRIBUTED THAT INCIDENT TO HAVING ACCIDENTALLY
HIT THE TRIGGER. IN 1993 I WAS PREPARING TO
UNLOAD THIS GUN AND IT FIRED WHEN I MOVED THE
SAFETY TO "F" TO UNLOAD. HOWEVER, I COULD NOT
DUPLICATE THAT MALFUNCTION. AGAIN I THOUGHT IT
WAS MY ERROR. THIS YEAR I MOVED THE SAFETY
FROM "S" TO "F". I HAVE BEEN VERY CAREFUL TO
STAY AWAY FROM THE TRIGGER HOUSING WHEN DOING
THIS. THIS TIME IT ONCE AGAIN FIRED WHEN THE
SAFETY WAS MOVED. THIS TIME I AM POSITIVE
THAT THE TRIGGER WASN'T TOUCHED. IT HAS TO BE
A MALFUNCTION.

My Name is Michael Mickener

298 PLEASANT ST

ROCKY NY 12472

Work phone 518-643-7188 7^{AM} TO 3^{PM}

Home phone 518-643-9395 3^{PM} ON.

THANK YOU IN ADVANCE FOR YOUR ATTENTION

Sincerely

Michael Mickener