

File Number:	9899	Arms Service number:	9721867
Last Name:	SMITH	First Name:	JAMES
Street:	21311 CR 466	City:	LINDALE
State:	TX	Zip:	75771
Work Ph:		Home Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1008		
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ
			UNJ UNC UND J
Settlement Detail:	REPAIR AT SPECIAL PRICE	Settlement Amount:	\$0.00
Date Closed Rem:	12/12/97	Date Closed by R/S:	12/12/97
Date of Incident:		Caliber:	243
Date Closed:	12/12/97	Bullet Weight:	
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	700	Serial:	6603892
Date Code:	RW	Date Mfgd:	11/1/72
RAMAC:	700	Litigation:	☐
		PreLitigation:	☐
		Obsolete:	☐
Custody:		Comments:	
Time of Modification:	1:31:39 PM	Date of Modification:	12/12/97

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL JJM		CUSTOMER ORDER NO.		ATTN JACK KAST		R 97-21867	
DATE RECEIVED 12/10/97	DATE OPENED 12/12/97	DATE CODE RW 11-72	SERIAL NUMBER 6603892	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL	
ACCESSORIES L/SIGHTS		W/STUDS					
FROM:				SHIP TO:			
SMITH, JAMES W 21311 CR 466 LINDALE				SMITH, JAMES W 21311 CR 466 LINDALE			
TX 75771				TX 75771			
CUST NO: 179261 C.O.D.							
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA	UPS	
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			REPAIR CHARGE 28.00 EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 36.00				
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE		B1					
TRIGGER GROUP		B2			E1		
BOLT ASSY.		B3			E2		
BARREL ASSY.		B4			E3		
REC. ASSY.		B5			E4		
WOOD					E5		
METAL							
MAIN FAULT <i>Left mfg 1972 upon receipt we could not duplicate the reported concern, but did note that the trigger only 4 stop screws have been tampered with. A check out adjustment has been applied. The bolt stop release is working slightly from being bound with gummy sticky substance.</i>							
<i>#26345</i> <i>1008</i> <i>4006</i>			COMMENTS <i>Replace the complete trigger assembly & clean action at 1/2 the normal repair charge.</i>				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY

H06525 REV. 7-97

To Jack Rast

5

This is the gun I spoke to you about
about going off accidentally.

I had layed it on the seat of my
Pickup, and dump the shells out of
the botton. I had a hold of the end
of the stock and took hold of the bolt
to take the shell out of Chamber the
gun fired.

I had just purchased the gun about
3 months ago as a used gun. I have
another 700-243 I have had about 16 yrs.
and my son has one we purchased in 1985
and we love both of them.

James W Smith

21311 CR 466

Lindale, TX 75771

Ph# 903 882 4016