

File Number:	9887	Arms Service number:	9721430
Last Name:	STUTLER	First Name:	JEFF
Street:	RT 1 BOX 479	City:	LUMBERPORT
State:	WV	Zip:	26386
Home Ph:		Work Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1008	Concern:	FIRE ON BOLT CLOSING
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANITA	Classification:	UNJ
Settlement Detail:	REPAIR AT SPEC. PRICE	Settlement Amount:	\$0.00
Date Reported - Reins:	12/8/97	Date Reported by PCS:	12/10/97
Date of Incident:		Date of Loss:	12/10/97
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	A6567118
RAMAC:	700	Date Code:	LQ
Caliber:	270	Bullet Weight:	
Manufacturer:	REM	Date Mfgd:	2/1/78
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Obsolete:	<input type="checkbox"/>	Comments:	
Custody:		Time of Modification:	10:58:35 AM
Date of Modification:	12/11/97		

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-21430

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/05/97

12/08/97

LQ 2-78

A6567118

700 270

CLASSIC

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

STUTLER, JEFF
RT 1 BOX 479
LUMBERPORT

WV 26386

STUTLER, JEFF
RT 1 BOX 479
LUMBERPORTWV
26386

CUST NO: 178847 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

28.00

8.00

36.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Cycle went off when pushing bolt down

MAIN FAULT

Upon receipt we could not duplicate this reported concern, but did find during our examination that the trigger & bolt stop were worn resulting sluggish from the complete action & trigger housing assembly. Could wear a heavy grimey sticky substance. Rifle has been poorly maintained.

*#26345 1008
4015*

COMMENTS

*Replace the complete trigger
assembly & clean the action at 1/2
the normal repair cost - good work*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

406925 REV '97

12 1 97

Jeff Stutler
Rt # 1 Box 479
Lumberport WV

26386

(304) 783-5178

Dear Sirs:

I have ~~this~~ Remington Model 700 Classic I purchased in 1979. The gun has worked flawlessly until two years ago. When I loaded the gun and was closing the bolt as I pushed it down the gun went off. I tried this without any shells and the same thing happened.

I took the gun to a qualified gunsmith and he cleaned the bolt's inside parts. The gun worked well until this deer season. I put a shell into chamber, put gun on safe and put bolt down, everything alright until I was getting ready to shoot, pushed gun off safety and gun fired.

If you need additional information, please contact me at (304) 783-5178.

Thank you,

Jeff Stutler