

File Number:	9956	ANHS Record Number:	9722709
Last Name:	TATRO	First Name:	TERRY
Street:	320 GOLF COURSERD	City:	RICHFORD
State:	VT	Zip:	05476
Home Ph:		Work Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1007	Concern:	FIRED ON SAFE RELEASE
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assignment To:	SANITA	Classification:	UNJ
Settlement Detail:	EXCHANGE UPGRADE, CHARGE DIFF. PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	12/20/97	Date Opened by PS:	12/22/97
Date of Incident:		Date of Loss:	12/22/97
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	ML010065
RAMAC:	700	Date Code:	PQ
Custody:		Date Mfgd:	6/1/96
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Obsolete:	<input type="checkbox"/>	Comments:	
Time of Modification:	11:25:00 AM	Date of Modification:	12/22/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-22709

INITIAL

CUSTOMER ORDER NO

JJM

BOTTOM HALF OF SEE THRU MOUNTS ONLY
ATTN DENNIS SANITA

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/18/97

12/20/97

PQ 6-96

ML010065

700 50CAL

ML

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

TATRO, TERRY
320 GOLF COURSERD
RICHFORD

VT 05476

TATRO, TERRY
320 GOLF COURSERD
RICHFORDVT
05476

CUST NO: 149530 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

200.00
8.00
208.00

W/STUDS # 802-848-7718

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP						
BOLT ASSY.						
BARREL ASSY.						
REC. ASSY.						
WOOD						
METAL						

MAIN FAULT

Upon receipt we could not duplicate the reported concern, but did find rust on the safety cam & trigger pin. Agreed to credit ML toward

Model 700 Mountain with dummy police Commission 12/22/97.

PARTS

COMMENTS

but also found under scope base. Found rusted - customer will replace in Feb. 98

Supply replacement m/700 Mountain with 30/06 (925859)

New #
in supply

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

WIP ML after repair

OFFICE COPY

RD6925 REV 7-97

Date: December 10, 1997

Dear Remington:

I purchased a Remington 700ML from AlderRun Gun Shop in Franklin Vt. I was hunting in the mountains on Sunday Dec 6. After sitting for awhile I decided to see how loud the safety was by putting to the fire position. The gun discharged. Thinking I had my finger on the trigger, I then cocked the gun and tried empty, the bolt went forward. It did this several times until the gun was varmed, then it no longer happened. Alder Run says he had one last year that did the same thing. These are the conditions we hunt in with muzzle-loaders. I'm not asking for this gun to be repaired but inspected by your facility to see what can be defected with the safety. Oh we can say cleaning or weather but we all know they still should be safe. I'm asking for a credit toward another firearm, I do not want this one returned. I will take a Model 700 mountain rifle and I'm willing to pay the difference. Caliber 30-06. I currently own many remington firearms and have never had any problems. A little bit of history about myself;

- 1) Hunter Education Instructor for St of Vt.
- 2) Hold record for largest buck ever taken in Vt with a muzzleloader.
- 3) Corporate Quality Director for a major company.
- 4) Bagged 39 deer.

Please honor my request for trading.

Thank-You

Terry Tatro
320 Golf Course Rd
Richford Vermont 05476

802-848-3387

P.S.

I did Not have the Proper
Tools to Remove Scope Mounts.