

File Number:	9155	Arms Service number:	9704276
Last Name:	TEAGUE	First Name:	MARK
Street:	501 DAVIS ROAD #B107	City:	LEAGUE CITY
State:	TX	Zip:	77573
		Home Ph:	281-332-6692
Work Ph:		Product Type:	F F A T
Type Concern:	S	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPLACE FC AT 1/2 NORMAL PRICING	Settlement Amount:	\$25.00
Date Opened Rem:	2/17/96	Date Opened by P/S:	2/17/96
		Caliber:	270
Date of Incident:		Date Closed:	2/18/97
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	700	Serial:	S6219561
		Date Code:	EM
RAMAC:	700	Date Mfgd:	10/1/92
		Litigation:	☐
		PreLitigation:	☐
		Obsolete:	☐
Custody:		Comments:	Replace firecontrol and check the firearm over completely - Could not duplicate customer concern - sticky residue and altered adjustments - 2/18/97
Time of Modification:	9:49:16 AM	Date of Modification:	2/18/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-04276

PRODUCT SERVICE W/TASCO 3X9 SCOPE

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/11/97	02/17/97	EM 10-92	S6219561		700 270 SS/SNY
ACCESSORIES	SOFT CASE	SCOPE MNTS	SCOPE BASE	SLING STRAP	W/STUDS
W/SWIVELS					

FROM:

SHIP TO:

TEAGUE, MARK
501 DAVIS RD #B107
LEAGUE CITY TX 77573

TEAGUE, MARK
501 DAVIS RD #B107
LEAGUE CITY TX
77573

CUST NO:162318 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

"FSR"

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Could not duplicate customer concern
ALTERED trigger screw adjustments and
sticky residue

PARTS

COMMENTS

REPLACE FIRECONTROL AND
check over completely at 1/2 normal
price
FLS 2/18/97

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

PS 34891

To Whom it May Concern:

This rifle on 2 separate occasions "fired" when I flipped the "Safety" lever from the "S" position to the "F" position. As this has never happened to me before, I am almost positive I did not accidentally pull the trigger.

I compared the trigger pull on this gun to several other rifles I own and it seemed lighter. I bought this gun from a used gun shop and I now suspect the "pull" has been tampered with. Also the "S" position feels a little spacy or soft.

I leave repair and notify me of your findings.

MARK TEAGUE
501 DAVIS RD. #B107
LEAGUE CITY, TEXAS 77573
PH. 281-332-4692

Thanks!