

File Number:	9777	Advisory Number:	9719900
Last Name:	WARRICK TRUE VALUE	First Name:	
Street:	213 S. MAIN ST	City:	BLAKELY
State:	GA	Zip:	31723
Home Ph:		Work Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1007		
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Certification:	UNJ
			UNJ UNC UND J
Settlement Detail:	REPAIR AT SPECIAL PRICE	Settlement Amount:	\$35.00
Date Reported Recd:	11/18/97	Date Reported by PSA:	11/18/97
Date of Incident:		Date Closed:	11/18/97
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	700	Serial:	6597511
Date Code:	EW	Date Mfgd:	10/1/72
RAMAC:	700	Litigation:	☐
		PreLitigation:	☐
		Obsolete:	☐
Custody:		Comments:	RIFLE POORLY MAINTAINED
Time of Modification:	10:34:26 AM	Date of Modification:	11/18/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

R 97-19900

INITIAL CUSTOMER ORDER NO.

ATTN JACK KAST

JJK

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/17/97

11/18/97

EW 10-72

6597511

700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

WARRICK TRUE VALUE HOME & AUTO
ATTN: AL
213 S MAIN ST
BLAKELY

GA 31723

WARRICK TRUE VALUE HOME & AUTO
ATTN: AL
213 S MAIN ST
BLAKELY

GA

31723

CUST NO: 031000 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE 28.00

EXCISE

TAX

INSURANCE

UPS 8.00

PARCEL POST

TOTAL 36.00

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

C2

METAL

C3

MAIN FAULT

11/19/97

Upon receipt we could not duplicate the reported
problem, but did note that the bolt stop release and trigger were
sloppy. Examination revealed that the bottom end trigger housing was
ground with rust, dirt, & a heavy sticky substance. Rifle has been
poorly maintained. The stop screws they say were loose also had
rust.

PARTS

COMMENTS

Replace the complete trigger assembly.
& Clean the bottom of the
trigger housing.

#26345

1007

4006

4015

go ahead

REMAIN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

AD6025 REV 7-97

07603

BERRICK'S *TrueValue* HOME & AUTO213 S. MAIN STREET
BLAKELY, GA 31723
(912) 723-3191

PAID BY		DATE 11-5-97	
NAME <i>Demetrius</i>			
ADDRESS <i>100 (JACK KAST)</i>			
CASH	C.O.D.	CHARGE	ON ACCT.
<i>9000 price when you</i>			
<i>buy safety to</i>			
<i>fire</i>			
<i>Rupia DSAP</i>			
<i>SOLD 10-30-96</i>			
<i>IN WARRANTY</i>			
<i>Demetrius 700 BDL</i>			
<i>30-86</i>			
RECEIVED BY <i>SN - 659751</i>			

AUTOMATIC BUSINESS PRODUCTS CO. WILLIMANTIC, CT 06226

D66

Thank You

All claims and returned goods MUST be accompanied by this bill.