



Customer Service Data Entry

IND	smk								
File Number:	8916	Arms Service number:	8627681						
Last Name:	WILDER,	First Name:	TIM						
Street:	C/O M-C RATHER	City:	MT JULIET						
State:	TN	Zip:	37122	Home Ph:					
Work Ph:		Product Type:	F	F A T O					
Type Concern:	S	PI PD P S C	Concern Code:	1007					
Concern:	FIRED ON SAFE RELEASE								
Cause Code:	400F	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS						
Assigned To:	KAST	Classification:	UNJ	UNJ UNC UND J					
Settlement Detail:	REPLACE TRIG N/C	Settlement Amount:	\$40.00						
Date Opened Rem:	12/18/96	Date Opened by P/S:	1/7/97	Caliber:	7MMMAC				
Date of Incident:		Date Closed:	1/7/97	Bullet Weight:					
Date to Analysis:		Date from Analysis:		Manufacturer:	REM				
Model:	700	Serial:	86204387	Date Code:	WM	Date Mfgd:	8/1/92		
RAMAC:	700	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>		
Custody:		Comments:	pounds pull and overtravel scr's altered - rust on trig pivot pin & hole						
Time of Modification:	1:37:55 PM	Date of Modification:	1/7/97						

Form View

FLTR

NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 96-27681INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED

12/11/96

DATE OPENED

12/18/96

DATE CODE

WM 8-92

SERIAL NUMBER

S6204387

NEW SERIAL NUMBER

MODEL AND GRADE

700 7MMAG

SS/ADL/SNY

ACCESSORIES

W/STUDS

SCOPE BASE

Prod. Service

FROM:

WILDER, TIM
C/O M C RATHER
11791 CENTRAL PIKE
MT JULIET,

TN 37122

SHIP TO:

WILDER, TIM
C/O M C RATHER
11791 CENTRAL PIKE
MT JULIET

TN

37122

CUST NO: 157767 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER INC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

METAL

MAIN FAULT

Firearm when safe was pushed to off.
Reflex safety stuck in fire position. Required
by W.H. McGraw. Gun fired when safe was
taken off after gun was repaired.
Unable to duplicate customer concern as rec'd. Took
trig. Assy. apart and found rust on trig. and pivot pin
hole. Exchange trig. at N/C due to poor hard off safe
condition.

PARTS

COMMENTS

Trig pull 4 1/2 LBS as rec'd.

See engagement ok
Trig adjusted outside of factory
not recommended.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 6/96

PS 34971

**Remmington Arms
Repair**

December 3, 1996

In January of 1996, the safety mechanism of this rifle stuck on the "safe" position. W.H. McGuns, in Humboldt, TN repaired the rifle. Since that time, less than 20 rounds have been fired from this rifle.

On November 23, 1996, I was hunting with this rifle. I pushed the safety to the "off" position and the rifle fired. To make sure that the trigger had not been accidentally depressed, I unloaded the rifle and cocked it. I flipped the safety on and off several times over a 20 minute period. The rifle dry-fired once when I flipped the safety to "off" during this period.

Model 700 Stainless Synthetic 7mm Rem. Mag.

Serial # S6204387

I can be reached at (615) 885-9904 (home) or (615) 650-7252 (work).

Please return the rifle to:

Tim Wilder
c/o M C Rather
11791 Central Pike
Mt. Juliet, TN 37122

Sincerely,



Tim Wilder
1321 Presidential Trace, Hermitage, TN 37076