

File Number:	9706	Arms Service number:	9718399
Last Name:	WITTENBU	First Name:	RG, ALBERT K
Street:	2840 122 AVE SE	City:	VALLEY CITY
State:	ND	Zip:	58072
Work Ph:		Home Ph:	701 845 1153
Type Concern:	S	Product Type:	F A T O
Concern:	FIRED ON BOLT CLOSING	Concern Code:	1008
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	KAST	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR SPCL PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	10/27/97	Date Opened by P/S:	10/29/97
Date of Incident:		Date Closed:	10/29/97
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	56276421
RAMAC:	700	Litigation:	
Custody:		PreLitigation:	
		Comments:	
		Caliber:	25-06
		Bullet Weight:	
		Manufacturer:	REM
		Date Mfgd:	7/1/96
		Obsolete:	
Date of Modification:	6:44:35 AM	Date of Modification:	10/29/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-18389

INITIAL

CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

10/24/97

10/27/97

0Q 7-96

E6276421

700 25-06

VS/SENDERO

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

WITTENBURG, ALBERT K.
2840 122 AVE SE
VALLEY CITY

ND 58072

WITTENBURG, ALBERT K.
2840 122 AVE SE
VALLEY CITYND
58072

CUST NO: 172850 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

10/28

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

ATTN: PRODUCT SERVICE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

\$123.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

E2

BARREL ASSY.

REC. ASSY.

B5

D2

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Unable to duplicate customer concern as read.
all trigger adjusting screws have been altered outside
of factory. Exchange trig. at a special price strictly
for a get me of good will.

PARTS

trig. Assy. -

COMMENTS

Action sits in stock OK
But BBL channel is too close
to bbl. open inletting.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

BWT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7-97

Jeff,

9-12-97

Enclosed is the gun we talked about on the phone. It has 2 problems I need fixed.

1st problem: Barreled action sits ccw in stock. I think metal stock insert was bedded wrong. I would like to have a new stock, ~~and~~ if you see fit.

2nd problem: when closing the bolt fast or "smartly", the firing pin would fire. I adjusted the trigger to fix the problem, but I don't know if I did it correctly. I talked to Gary on the phone and he said it may be possible to put in a new factory trigger. Please re-adjust trigger (to $\frac{3}{16}$ in.) or install a new one.

If any of these problems cannot be fixed on warranty, please call me early mornings.
Thank you

Ship to:

Albert K Wittenberg

701-845-1153

2840 122 Ave SE

Valley City, ND 58072