

File Number:	9644	Arms Service number:	9717604
Last Name:	YARINA	First Name:	LEONARD
Street:	1167 PINE STREET	City:	JOHNSTOWN
State:	PA	Zip:	15909
Home Ph:	814-536-4638		
Work Ph:		Product Type:	F A T
Type Concern:	S	PI PD P S	Concern Code:
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND
Settlement Detail:	REPLACE FC N/C WITH NEW STYLE		Settlement Amount:
Date Opened Rem:	10/14/97	Date Opened by P/S:	10/14/97
Date of Incident:	7/1/97	Date Closed:	10/28/97
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	A6688568
RAMAC:	700	Date Code:	RD
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Custody:		Obsolete:	<input type="checkbox"/>
Comments:	Rifle covered with protective grease. Could not duplicate concern - Replace FC with current style w/o bolt lock at n/c		
Time of Modification:	2:52:00 PM	Date of Modification:	10/14/97

Update 10/28/97

File Number: 9644		Arms Service number: 9717604	
Last Name: YARINA		First Name: LEONARD	
Street: 1167 PINE STREET		City: JOHNSTOWN	
State: PA	Zip: 15909	Home Ph: 814-536-4638	
Work Ph:	Product Type: F	F A T	
Type Concern: S	PI PD P S	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4015	Cause: IMPROPER MAINTENANCE		
Assigned To: SUPRY	Classification: UND	UNJ UNC UND	
Settlement Detail: REPLACE FC N/C WITH NEW STYLE	Settlement Amount: \$50.00		
Date Opened Rem: 10/14/97	Date Opened by P/S: 10/14/97	Caliber: 270	
Date of Incident: 7/1/97	Date Closed:	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: A6688568	Date Code: RQ	Date Mfgd: 11/1/78
RAMAC: 700	Litigation: <input type="checkbox"/>	PreLitigation: <input type="checkbox"/>	Obsolete: <input type="checkbox"/>
Custody:	Comments: Rifle covered with protective grease. Could not duplicate concern		
Time of Modification: 2:52:00 PM		Date of Modification: 10/14/97	

Leonard Yarina
1167 Pine Street
Johnstown, Pa. 15909
October 8, 1997

REMINGTON ARMS CO.
Attn. Fred Supry
14 Hoesler Ave.
Illion, New York 13357

Gentlemen:

I am returning this rifle to be checked as per my conversation with
Mr. Supry.

The problem occurred when I went to unload the cartridge that was in the chamber. After taking the safety off, so that I could open the bolt, when I went to move the bolt from the closed position to open it, the rifle discharged. Luckily the muzzle was pointing into the ground and no one was hurt. I am now afraid to let anyone of my boys use this gun for fear it will again do the same thing. After talking to the local sporting goods store, I was told that there was a problem with the trigger/safety assembly a while back. This gun I have owned for some time and have only recently started to use it and let my boy use my 760. There can not have been more than 80 rounds fired through this rifle. I hope that you can have it repaired and returned before the end of November for our deer season.

Thank you,

Leonard Yarina