

	AND ESTI	MATING	REPORT							R 99	ORDER 7-21431	
TEF CUSTOME	R ORDER NO.											
	DATE OPENED	DATE CO	DE	SERIAL NUMBER	NEW SERIA	NUMBER	MODEL AND	GRADE				
10/29/99		1	10-66	246246			700	27	Ø	F	BDL.	
ACCESSORIES	W/ZIUD	2	ZCOPE		- L							
	· · ·			L/REAR S	GT ASS	Y						
FROM:	Г					٦	SHIP TO:					
		IN, JOE				•	BAZIN	. J0	E			
			STREET				4024		9 ST	REET		
	TOP	EKA		. KS 6	6610		TOPEK	A .			KS 56610	
				-							0010	
				CUST NO): 05 527:	f C.ÆD.i	p∟					
ACCOUNT NUMBER		ACCOUNT NU	MBER N/C]			PROM. DATE		ESTIMATE	ED V	VIA	
CLE LOCK DITION		<u> </u>		WRITE			<u> </u>			1	UPS	
GUN CONDITION									,	REPAIR C	HARGE	
☐ NEW										EXCISE		
LIGHTLY WORN					1.		٠.,		. :	TAX		
WORN				•	42		INSURANCE					
VERY WORN			1	•	* 4\$					UPS		
UNREPAIRABLE 1				Servi	· ·		PARCEL POST					
MARRED			v.04 (\$					TOTAL	L	
CUSTOMER CON	CERN	AMMO	FUNCT	ION FINIS	H A	CCURACY	FiT	-	II.	SPECT		
CYCLE	At	ı	B1 ·			11			ļ			
TRIGGER GROUP			B2 .:	<u> </u>		•	E1		F1			
BOLT ASSY.		· ·	B3	· •			E2	· .	F2			
BARREL ASSY.		.'	B4		D1	•	E3	· .	F3			
REC. ASSY.		v'	B5		02		E4	<u>'`</u>	F4			
WOOD				C1	, D3	·	, E5		F5		***	
METAL			17	C2	7	7						
MAIN FAULT			Cou	N NOT 1	UPLICA	H.						
`s.												
			•				ή,					
	·						*					
						*						
												
PARTS				CO	MMENTS ,	Penlar	TPA		2 <	neul	100	
						KPIAG	- ////		- Pf	Test 1	price	
				1.	· · · · · · · · · · · · · · · · · · ·	•						
		··-				·					· · · ·	

	r			-								
	v											
		· · · · · · · · · · · · · · · · · · ·										
					<u> </u>							
				RE	ARIVAN	PROOF	CLEAN	TES	3T	TARGE	T PAT	
				nc.	A13		CLEAN	TES	37	TARGE	т РАТ	
				RE/	AFRYAN A	PROOF	CLEAN	TES		TARGE	T PAT	

Remington Arms Services Attn: Customer Repairs 14 Hoefler Ave. Ilion, NY 13557

Dear Sirs,

Enclosed please find a Model 700, BDL in .270 Cal., serial # 246246. I have experienced a problem which I am hoping you can repair before the upcoming deer season. Sometimes when the action is "worked" the hammer drops when the bolt is closed.

The gun has been used very little and possibly some lubricant as "gummed up" the trigger spring, which prevents the trigger from being returned to a neutral position. Maybe?

Thank you for your assistance in this matter and please advise any expense involved.

Sincerely,

Joe Bazin, owner 4024 SW 39th St.

Topeka, KS 66610-1151

W785-267-2932 M-F 7:00-4:30 CST

H785-267-2932