

File Number:	11182		Arms Service number:	9901874	
Last Name:	BYRANSTEENS GUNS & ARCHERY			First Name:	
Street:	2840 PETERS CREEK ROAD NW			City:	ROANOKE
State:	VA	Zip:	24019	Home Ph:	
Work Ph:	540-562-GUNS	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S G	Concern Code:	1020	
Concern:	FIRED ON BOLT OPENING				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	REPLACE FC AT SPECIAL PRICE			Settlement Amount:	\$0.00
Date Opened Rem:	02/21/1999	Date Opened by P/S:	01/25/1999	Caliber:	270
Date of Incident:		Date Closed:	01/26/1999	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	D6248433	Date Code:	W/O
Date Mfgd:	08/01/1996				
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	Could not duplicate customers concern - Adjustment screws were altered from the factory settings - Replace FC at special price - check gun over for bluing concerns		
Time of Modification:	4:29:37 PM		Date of Modification:	01/26/1999	

BRYANSTEENS GUN & ARCHERY
2840 PETERS CREEK PARKWAY
ROANOKE, VIRGINIA 24019
540-562-GUNS

TO: REMINGTON

ATT: REPAIRS

ENCLOSED IS ONE OF YOUR
MODEL 700 LEFT HAND RIFLES #06248433
IT WAS RECENTLY BROUGHT BACK TO
US BY A CUSTOMER. HE STATED THE
GUN HAD FIRED WHEN HE TRIED TO EJECT
A LIVE CARTRIDGE. IT ALSO HAD BLOWING
COME OFF NEAR THE END OF THE BARREL
THE FIRST TIME IT RAINED, EVEN THOUGH
HE WIPOD IT DOWN AS SOON AS HE GOT BACK.
PLEASE INSPECT AND REPAIR AS NECESSARY.

THANK YOU

PAUL Hyllton

MGR.

6451

12/30/88