

File Number:	12545		Arms Service number:	9923925	
Last Name:	CARROLL		First Name:	FRANK	
Street:	374 E 112TH PL		City:	NORTHGLENN	
State:	CO	Zip:	80233	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SANITA	Classification:	UNC	UNJ UNC UND	
Settlement Detail:	REPLACE TRIG ASSEM		Settlement Amount:	665.00	
Date Opened Rem:	12/6/99	Date Opened by P/S:	12/6/99	Caliber:	308
Date of Incident:		Date Closed:	12/7/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600	Serial:	79533	Date Code:	DN
Date Mfgd:	9/1/66				
RAMAC:	600	Litigation:	☐	PreLitigation:	☐
Obsolete:	☒				
Custody:		Comments:	RIFLE NEVER UPDATED		
Time of Modification:	1:29:39 PM		Date of Modification:	12/7/99	

Frank A. Carroll
374 E 112th Place
Northglenn, Co. 80233-302
November 21, 1999

Remington Arms Co., INC.
14 Hoefler Ave.
PO Box 179
Ilion, Ny. 13357

Gentle person:

Inclosed, please, find a modle 600,
serial number 79533. I have owned this
rifle since 1968, when I bought it from
J C Penney's in Kansas City, Mo. at state line
road.

The rifle fire pin engages the shell when
the bolt is closed. This action causes a
premature discharge of the weapon without
the trigger being engaged.

I am very fond of this weapon but
prefer a trigger pull of $(3\frac{1}{2})$ three and
one half pounds.

Sincerely,
Frank A. Carroll