

File Number:	11732		Arms Service number:	9915690	
Last Name:	DAWSON CO		First Name:		
Street:	2104 HARDY ST		City:	HOUSTON	
State:	TX	Zip:	77026	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SANITA	Classification:	UNJ	UNJ UNC UND	
Settlement Detail:	REPAIR AT SPEC. PRICE			Settlement Amount:	\$0.00
Date Opened Rem:	8/16/99	Date Opened by P/S:	8/16/99	Caliber:	7MM MAG
Date of Incident:		Date Closed:	8/17/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	E68195122	Date Code:	PP
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Custody:		Obsolete:	☐		
Comments:					
Time of Modification:	9:27:58 AM		Date of Modification:	8/17/99	

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 99-15690

INITIAL

CUSTOMER ORDER NO.

SENDER/SYN

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

W/STUDS

SCOPE BASE

E6819522

700

7MM.MAG

BDL

W/SCOPE RINGS

FROM:

SHIP TO:

DAWSON COMPANY
2104 HARDY ST
HOUSTON

TX 77026

DAWSON COMPANY
2104 HARDY ST
HOUSTONTX
77026

CUST NO: 213351 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NYC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE 35.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

D3

METAL

MAIN FAULT

Upon receipt we could not duplicate the reported problem, but
did find the action very dirty & not inside the trigger housing
properly. Rifle properly maintained. Trigger & fire very rusty.

PARTS

COMMENTS

2345

Replace the complete trigger
assembly & clean the action out
1/2 the normal cost

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Fred Sapping

Here is the rifle I talked to you about on the phone. My Sendero miss fired when I would flip the safety to fire. Luckily I had the rifle pointed out the window of my stand at a deer when it happened the first time. Then I tried to figure out what happened. With rifle pointed up I put another shell in the chamber. Nothing happened. I thought I might have bumped the trigger. Then I flipped safety to fire and blew a hole through the roof of my stand. Please check out my rifle and set trigger to 3 1/2 pounds. No one has touched the insides of this gun.

Gregorio phone
713-223-2551

Thanks
Dennis Potting

page # 713-217-1464

P.S. This is a great rifle. When I shot it for the first time I touched bullets with factory ammo at 200 yds on a lighted range at night.

DAWSON COMPANY
FOOD SERVICE EQUIP., PARTS & SERVICE
2104 HARDY ST.
HOUSTON, TEXAS 77028

TO REMINGTON ARMS SERV.
ATTN: CONSUMER REPAIRS
14 HOEFLE
ILION NY 13357
ATTN: FOOD SUPPLY