

File Number:	12543		Arms Service number:	9923926	
Last Name:	DEPOYS GUNS & SUPPLIES /STRICK		First Name:	CARL	
Street:	15175 MOUNTAIN VALLEY ROAD		City:	BROADWAY	
State:	VA	Zip:	22915	Home Ph:	540-896-8231
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code: 1007		
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	EXCHANGE TPA N/C		Settlement Amount:	\$40.00	
Date Opened Rem:	12/6/99	Date Opened by P/S:	12/6/99	Caliber:	270
Date of Incident:		Date Closed:	12/7/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	C6615115	Date Code:	RK
Date Mfgd:	11/1/90				
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	Talked to customer on phone - concern seemed to be more of delayed firing - Could not duplicate either Delay or FSR - Sticky, gummy residue on TPA - bolt release sluggish - Install new TPA, clean gun, and send owners manual n/c		
Time of Modification:	1:29:58 PM		Date of Modification:	12/7/99	

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-23926

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/03/99

12/06/99

RK 11/90

C6615115

700 270

BDL

ACCESSORIES

W/STUDS

L/REAR SIGHT

FROM:

SHIP TO:

DEPOYS GUNS & SUPPLIES
15175 MOUNTAIN VALLEY RD
BROADWAY

VA 22815

DEPOYS GUNS & SUPPLIES
15175 MOUNTAIN VALLEY RD
BROADWAY

VA 22815

CUST NO: 113452 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

230145

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Fire on Safe Release

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

N/C

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Could not duplicate customer concern
Sticky Gumay residue
- Bolt Release sluggish

Gun owner Carl Stecker

PARTS

COMMENTS

Install new TPA and
Clean gun -
Send new owners manual
No charge to customer FLS
12/7/99

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6525 REV. 7/97