

File Number:	12830		Arms Service number:	00000782	
Last Name:	GOMEZ		First Name:	RUBEN SR	
Street:	7122 MILKY WAY DR		City:	CORPUS CHRISTI	
State:	TX	Zip:	78412	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	Pi P D P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SANITA	Classification:	UNJ	UNJ UNC UND	
Settlement Detail:	REPAIR AT N/C		Settlement Amount:	\$50.00	
Date Opened Rem:	12/29/99	Date Opened by P/S:	12/29/99	Caliber:	
Date of Incident:		Date Closed:	12/30/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	B6703185	Date Code:	
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Custody:		Obsolete:	☐		
Comments:	REPAIRING N/C FOUND MORE THAN NORMAL FORCE REQUIRED TO MOVE SAFE				
Time of Modification:	8:37:19 AM		Date of Modification:	12/30/99	

Serial Number: B6708186

Model ID: 700



RE00000782

12/29/99

When you move sub the gun fires

Could not duplicate

The action & trigger assembly are covered with
heavy wet substance & dirt.

More than normal force required to move sub.

#26345

Replace trigger assembly & clean action at no charge

Chge 230145

12-8-99

Gentlemen : My 700 model fires
when you move the safety
button from safe to fire.
Please advise.

Thanks

Ruber H. Gomez Sr.
7322 Milky Way Dr.
Corpus Christi, TX, 78412

361-991-3233