

File Number:	11533	Arms Service number:	9910178
Last Name:	HORTON	First Name:	RANDY
Street:	4921 TOKIO ROAD	City:	WEST
State:	TX	Zip:	76091
Home Ph:	254-829-1995	Work Ph:	
Type Concern:	IS	Product Type:	F
Concern Code:	1007	Concern:	FIRED ON SAFE RELEASE
Cause Code:	9010	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED
Assigned To:	SLIPPY	Classification:	UND
Settlement Detail:	REPLACE FIRECONTROL N/C	Settlement Amount:	\$40.00
Date Opened Rem:	4/23/99	Date Opened by P/S:	4/23/99
Date of Incident:		Date Closed:	4/26/99
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	A6877777
RAMAC:	700	Date Code:	BA
Custody:		Date Mfgd:	1/1/90
Litigation:	☐	PreLitigation:	☐
Obsolete:	☐	Comments:	Could not duplicate concern. Some of sky residue inside firecontrol - Replace firecontrol n/c as gesture of goodwill
Time of Modification:	9:08:18 AM	Date of Modification:	4/23/99

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 99-10178

INITIAL
PS

CUSTOMER ORDER NO

W/PACHMAYR RECOIL PAD

DATE RECEIVED

-4/22/99

DATE OPENED

04/23/99

DATE CODE

SERIAL NUMBER

A6877777

NEW SERIAL NUMBER

MODEL AND GRADE

700 7MM EXP BDL

ACCESSORIES

W/STUDS

L/SIGHTS

BA 1-802ND TIME IN

FROM:

SHIP TO:

HORTON RANDY
4921 TOKIO RD.
WEST

TX 76691

HORTON RANDY
4921 TOKIO RD.
WESTTX
76691

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

230145

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

N/C

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

E5

F5

MAIN FAULT

Could not duplicate concern

PARTS

COMMENTS

Replace fire control AS
gesture of goodwill
N/C FLS 4/26/99

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Randy Horton
4901. Tolero Road
West, Texas 76641

Phone # 254-809-1995
fax # 254-809-0107

To whom it may concern;

I am sending you my Remington 700 BOL
7mm Express Rem. Aor report for the second time.
The problem is intermittent with the safety. Sometimes
when releasing the ~~safety~~ safety, the rifle will
fire. This recently caused me to miss a large
whitetail buck on my last hunt with this rifle.
But my main concern is accidentally having the
rifle fire and someone getting hurt or
damaging something. This rifle has always been
a lemon and I have had some custom
work done on it just to get it to group
factory ammo in a three inch circle. I
can reload and get this group down to 1.25
inches. When I first obtained this rifle it
would not group on a 9" pie plate! I
would hope that you can ~~rep~~ find and report
the problem with this rifle. ~~But~~ I am afraid
to try to use it in its present condition.
Your prompt and efficient service will
be greatly appreciated and is needed.

Thanks,
Randy Horton