

File Number:	12594		Arms Service number:	00000339	
Last Name:	MAYNOR		First Name:	KENNETH/NANCY	
Street:	132 KENNY LANE		City:	WEST MONROE	
State:	LA	Zip:	71291-4721	Home Ph:	318-396-5863
Work Ph:	318-396-1468	Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	1013	Cause:	BROKEN PARTS OR MISSING PARTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	REPLACE TPA N/C			Settlement Amount:	\$40.00
Date Opened Rem:	12/15/99	Date Opened by P/S:	12/16/99	Caliber:	
Date of Incident:		Date Closed:	12/17/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	A6840847	Date Code:	
RAMAC:	700	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
		Obsolete:	<input type="checkbox"/>		
Custody:		Comments:	As received the Sear connecting surface was chipped and broken away - the remaining part of the sear surface was making contact - Could not duplicate customers concern - Replace TPA at n/c as gesture of goodwill.		
Time of Modification:	10:45:14 AM	Date of Modification:	12/17/99		

Serial Number: A6840847

Model ID: 700



RE00000339

Could not Duplicate Concern

As Received the Sear was chipped  
And broken at the connecting surfaces.

Replace TPA n/c as gesture of  
goodwill.

FLS 12/17/99

New style  
Safety Arm

*Product  
Service*

132 Kenny Lane  
West Monroe, Louisiana 71291-4721  
November 15, 1999

*ABJ*

Remington Arms Company  
Dept. W  
14 Hoefler Avenue  
Ilion, New York 13357

Dear Sirs:

I am returning this rifle, Model 700 Remington Bolt Action, Serial No. A6840847 for a safety evaluation as per my phone conversation with your service department on November 8.

The reason for returning the rifle is because it discharged as my wife, Nancy, was opening the bolt while on a deer hunting trip on November 6. Nancy pushed the safety to the FIRE position. As she began the upward movement of the bolt, the rifle unexpectedly discharged, shooting a hole in the ground at her feet. Fortunately, no one was hurt and there was no property damage as a result of this discharge. However, I no longer have any confidence in this Model 700 Remington.

I also had the rifle checked at Ted's Gun & Reel, our local authorized Remington dealer in West Monroe, Louisiana, and was advised by the dealer to return the rifle to Remington for safety reasons.

Please check the rifle and notify me of your findings so we can discuss what actions need to be taken.

Sincerely,

*Kenneth Maynor*  
*Nancy Maynor*  
Kenneth Maynor  
Nancy Maynor

Home Phone: (318) 396-5963  
Work Phone: (318) 396-1468  
E-mail: kennan@colla.com