

File Number:	11270	Arms Service number:	9904495
Last Name:	MCBRIDES GUN SHOP	First Name:	
Street:	2915 SAN GABRIEL 30TH N LAMAR	City:	AUSTIN
State:	TX	Zip:	78705
Home Ph:		Work Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1008		
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNI
		UNI UNC UND J	
Settlement Detail:	REPAIR AT N/C GOODWILL	Settlement Amount:	\$0.0
Date Opened Rem:	02/13/1999	Date Opened by P/S:	02/15/1999
Caliber:	243		
Date of Incident:		Date Closed:	02/15/1999
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	700	Serial:	6204302
Date Code:	EO	Date Mfgd:	10/01/1994
RAMAC:	700	Litigation:	☐
PreLitigation:	☐	Obsolete:	☐
Custody:		Comments:	also rust found inside the trigger housing assembly
Time of Modification:	7:18:56 AM	Date of Modification:	02/16/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-04495

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/07/99

02/13/99

EO 10-94

6204302

700 243

SS/SYN/DM

ACCESSORIES

W/STUDS

SCOPE MNTS

FROM:

SHIP TO:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH N LAMAR

AUSTIN

TX 78705

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH N LAMAR

AUSTIN

TX

78705

CUST NO:006578 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

230145

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

D1

E1

F1

D2

E2

F2

D3

E3

F3

D4

E4

F4

D5

E5

F5

MAIN FAULT

Upon receipt we could not duplicate the reported concern.
Plum did reveal that the trigger adj screws have been re-set to below
3 lbs (2 3/4 lbs.) minimum. The trigger pin was also found
loose from unknown source.

PARTS

COMMENTS

Replace the complete trigger assembly.
& clean action at N/A.
W/ Gunsmith of Gunsmith

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6825 REV. 7/97

MCBRIDES, INC.

30TH AT N. LAMAR • AUSTIN, TEXAS 78705 • (512) 472-3532

MESSAGE

REPLY

Remington Arms Service
14 Hoefler
I Lion, N.Y. 13357
1/30/99

DATE

We are sending the enclosed
Rem 700 # T6204302 for a customer
who wants warranty inspection
because the gun slam fired.
Please check proper function.

JSde

SIGNED

Item # NF73 The Drawing Board, P.O. Box 2944, Hartford, CT 06104-2944
1982, Printed in U.S.A.

INSTRUCTIONS TO SENDER:

YELLOW COPY. 2. SEND WHITE AND PINK COPIES INTACT.

INSTRUCTIONS TO RECEIVER:

1. WRITE REPLY. 2. DETACH STUB, KEEP PINK COPY, RETURN WHITE COPY TO SENDER.