

File Number:	11181	Arms Service number:	9902287
Last Name:	MCKINNEY	First Name:	CHARLES F
Street:	3946 KENYON DRIVE	City:	MEMPHIS
State:	TN	Zip:	38125
Home Ph:	901-335-2007	Home Ph:	901-763-5764
Work Ph:	901-335-2007	Product Type:	F A T O
Type Concern:	IS	PI PD P S C	Concern Code:
Concern:	F I R E D O N S A F E R E L E A S E		
Cause Code:	4315	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND F
Settlement Detail:	REPLACE FC AT SPECIAL PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	01/23/1999	Date Opened by P.S.:	01/25/1999
Date of Incident:		Date Closed:	01/25/1999
Date to Analysis:		Bullet Weight:	270
Model:	700	Serial:	A6437070
RAMAC:	700	Date from Analysis:	
Custody:		Date Code:	AO
		Pre Litigation:	
		Litigation:	
		Comments:	Improperly cared for life - IPA so rusted that the bolt release would not move - Entire mechanism coated with rust - Replace FC at special price
Time of Modification:	10:29:17 AM	Date of Modification:	01/25/1999

File Number:	11161	Arms Service number:	9002287
Last Name:	MCKINNEY	First Name:	CHARLES F
Street:	3946 KENYON DRIVE	City:	MEMPHIS
State:	TN	Zip:	38125
Home Ph:	901-335-2007	Home Ph:	901-753-5764
Work Ph:	901-335-2007	Product Type:	F A T O
Type Concern:	JS	PI PD P S C	Concern Code:
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANITA	Classification:	UNJ UNO UNO J
Settlement Detail:	REPLACE FC AT SPECIAL PRICE		
Date Opened Rem:	01/23/1999	Date Opened by P/S:	01/25/1999
Date of Incident:		Date Closed:	01/25/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	AG437070
RAMAC:	700	Litigation:	
Custody:		Prelitigation:	
		Discrete:	
		Comments:	Improperly cared for rifle - TPA so rusted that the bolt release would not move - Entire mechanism coated with rust - Replace FC at special price
Date of Modification:	10:29:37 AM	Date of Modification:	01/25/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 99-02287

INITIAL
PS

CUSTOMER ORDER NO.

W/RECOIL PADL/REAR SIGHT W/ BOTTOM HALF OF SCOPE MOUNT

DATE RECEIVED
01/13/99

DATE OPENED
01/23/99

DATE CODE
AO 3-80

SERIAL NUMBER
A6437070

NEW SERIAL NUMBER

MODEL AND GRADE
700 270

BDL

ACCESSORIES

W/STUDS

FROM:

MCKINNEY, CHARLES F
3946 KENYON DR
MEMPHIS

TN 38125

SHIP TO:

MCKINNEY, CHARLES F
3946 KENYON DR
MEMPHIS

TN 38125

CUST NO: 204041 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

PROM. DATE

ESTIMATED

VIA

UPD

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

35.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

43.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5				F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt the rifle was in operation, the bolt stop & trigger were completely seized up from excessive use & dirt. Rest all over the rifle was in good shape. Rifle was properly maintained. Action also very dirty.

PARTS

COMMENTS

26345

1007

4015

Replace the complete trigger assembly & clean action at 1/2 the normal cost.
Cpt.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

1-12-99

Dear Mr. Sanita

As per our conversation, I'm sending you the rifle in question. This rifle fired on its own in my truck with the safety on shooting out two windows and came within inches of my wife's head. This happened at the first of deer season in November. The second time was this past Saturday - 1-9-99 as my wife was putting a shell in the chamber the gun fired, again, on its own. This time the shot missed myself and a fellow hunter.

We have been extremely lucky twice and the gun needs to be fixed.

Please let me know what your findings are. You can contact me during working hours on my mobile phone - 901-335-2001 or at home in the evenings at 901 753-5764.

Thank you for your help.

Sincerely

Charles F. McKinney
Charles F. McKinney
3946 Keynon Dr.
Memphis, TN. 38125