

File Number:	11623		Arms Service number:	9912650	
Last Name:	MIELE		First Name:	RAYMOND	
Street:	34 MIDLAND DR		City:	WALTHAM	
State:	MA	Zip:	02451	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	FD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	1013	Cause:	BROKEN PARTS OR MISSING PARTS		
Assigned To:	SANITA	Classification:	UND	UNJ UNC UND	
Settlement Detail:	REPAIR AT N/C		Settlement Amount:	€50.00	
Date Opened Rem:	5/11/99	Date Opened by P/S:	0/11/99	Caliber:	50
Date of Incident:		Date Closed:	6/14/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	ML006181	Date Code:	PC
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Custody:		Obsolete:	☐		
Comments:	TRIGGER CONNECTOR FOUND BROKEN AT THE STOP SCREW HOLE				
Time of Modification:	2:43:53 PM		Date of Modification:	6/14/99	

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
Service

ORDER

R99-12550

INITIAL
RLP

CUSTOMER ORDER NO.

L/ACCESSORIES

DATE RECEIVED

06/10/99

DATE OPENED

06/11/99

DATE CODE

PQ 6-96

SERIAL NUMBER

ML005161

NEW SERIAL NUMBER

MODEL AND GRADE

700 50 CAL

ML

ACCESSORIES

W/STUDS

FROM:

MIELE, RAYMOND JR
34 MIDLAND DR
WALTHAM

MA 02451

SHIP TO:

MIELE, RAYMOND JR
34 MIDLAND DR
WALTHAM

MA

02451

CUST NO: 210842 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

230145

WRITE ☐

PROM. DATE

ESTIMATED

VIA

6-14-99 UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Upon receipt the rifle was in operation
Upon removal a broken trigger connector at the center of the stop
pin hole.

PARTS

COMMENTS

Repair the connector
trigger arm at no charge

REPAIRMAN

KRS

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7-97

8 June 99

Dear Sir

Could you please check my Remington 700 ML for me. I bought the rifle new in July 1996, receipt enclosed. The rifle is not functioning correctly in regards to the safety. I was shooting it at the range last week & when I tried to fire my last round I could not pull the trigger back.

When I got home I removed the charge according to my Rem manual on pages 23 & 24. After unloading rifle & cleaning it I checked what I could & this is what I found. With the bolt open the safety works both on & off. With bolt out of rifle safety works on & off.

When I put bolt back in rifle & push safety from safe to fire the rifle goes off without my touching the trigger. I have not tried to adjust the trigger on this rifle its excellent as is just like my Rem 700 7mm mag. I am using Pyrodex RS - 50-60 grs with 275 gr Rem JHP bullet with shot & Rem #10 caps. I don't use black powder because I have to drive 100 miles from over

home to buy it & the Pyrodey seems to
burn somewhat cleaner. Please let me
know what you find out is ~~wrong~~^{wrong}
with my rifle as I really enjoy shooting
it. Thank you.

Yours truly

Donald J. Gould

368 Earle Dr.

Carleton, Mich.

48117

Serial # of Rifle

ML-005161

Phone 734-654-9659