

File Number:	11235	Arms Service number:	9903437
Last Name:	MITCHELL	First Name:	ERNEST
Street:	4816 CANTERBURY WY	City:	ANCHORAGE
State:	AK	Zip:	99503
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F F A T
	PI PD P S	Concern Code:	1020
Concern:	FIRED ON BOLT OPENING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT SPEC PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	02/03/1999	Date Opened by P/S:	02/03/1999
Date of Incident:		Caliber:	30/06
		Date Closed:	02/04/1999
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	700	Serial:	6681915
		Date Code:	RX
RAMAC:	700	Date Mfgd:	11/01/1973
Litigation:	☐	PreLitigation:	☐
Obsolete:	☐		
Custody:		Comments:	POOR CARE
Time of Modification:	6:55:31 AM	Date of Modification:	02/05/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-03437INITIAL
PS

CUSTOMER ORDER NO.

DATE RECEIVED
01/27/99DATE OPENED
02/03/99

DATE CODE

RX 11-73

SERIAL NUMBER

6681915

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

W/STUDS

SOFT CASE

SCOPE MNTS

FROM:

MITCHELL ERNEST L.
4816 CANTERBURY WY.
ANCHORAGE

AK 99503

SHIP TO:

MITCHELL ERNEST L.
4816 CANTERBURY WY.
ANCHORAGEAK
99503

CUST NO: 203958 C.O.D.L.

ACCOUNT NUMBER

2293001

ACCOUNT NUMBER N/C

WRITE ☐

PROC. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

25.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

33.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4				F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT

Upon receipt we could not duplicate the above concerns, but did find the trigger pin rusty & the rear end screw has been tampered with. Mfg 1973

COMMENTS

Replace the complete
trigger group & clean action
at 1/2 the normal charge

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7-97

1-12-99

DEAR SIR;

IN Sept. 07 1978 This Rifle fired AS IT WAS being unloaded. There were Two Rounds in the Rifle and one Round in the chamber AS I Rotated the Bolt To Remove these Rounds the Rifle fired AS The bolt WAS Rotated about halfway. The Trigger WAS NOT Touched.

The Rifle has NOT been loaded or fired since. I have also been unwilling To sell or dispose of it for the same Reason.

I Recently learned that there have been other Remington 700 ADL's that have done the same thing and that Remington had a fix that would preclude it happening again. Please do this if possible.

If there is a change involved Please Advise me be for Taking Action.

my Address is: ERNEST L. MITCHELL
4816 CANTERBURY WAY
ANDOVER MA 01903

my Phone Number is 907-561-2568

When the Repairs are completed I
would like for you to Return the
Rifle To: Lori Caves

111 Myrick St
Headland AL 36345

I Purchased this Rifle (96681915)
IN 1974.

Thank you
Ernest L. Mitchell

ERNEST L. MITCHELL
4816 CANTERBURY WY
ANCHORAGE AK
99503

907-561-2568

When Repairs are
Complete Ship To:

LORI CAVES
111 MYRICK ST.
HEADLAND AL
36345