

File Number: 11344		Arms Service number: 9906267	
Last Name: PARKER		First Name: CECIL	
Street: RR 3, BOX 3415		City: TRINITY	
State: TX	Zip: 75862	Home Ph: 409-594-7336	
Work Ph:	Product Type: F	F A T	
Type Concern: PI	PI PD P S	Concern Code: 1007	
Concern: FIRED ON-SAFE RELEASE			
Cause Code: 4015	Cause: IMPROPER MAINTENANCE		
Assigned To: SUPRY	Classification: UNJ	UNJ UNC UNB	
Settlement Detail: REPLACE FC N/C - SEND OWNERS MANUAL	Settlement Amount: \$40.00		
Date Opened Rem: 03/05/1999	Date Opened by P/S: 03/05/1999	Caliber: 270	
Date of Incident: 01/03/1999	Date Closed: 03/05/1999	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: A6202035	Date Code: DZ	Date Mfgd: 09/01/1975
RAMAC: 700	Litigation: ☐	PreLitigation: ☐	Obsolete: ☐
Custody:	Comments: Adjustments altered to unsafe condition - minimal sear engagement - FC sluggish from sticky, gummy residue - As received the bolt release was stuck - It had to be forcefully moved using a screwdriver because of the sticky residue		
Time of Modification: 3:31:39 PM		Date of Modification: 03/05/1999	

RECEIVING ESTIMATING REPORT

COMMENTS

ORDER
R 99-06277

W/RECOIL PAD

DATE RECEIVED 02/27/99	DATE OPENED 03/05/99	DATE CODE DZ 9-75	SERIAL NUMBER A6202035	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	BDL
ACCESSORIES W/STUDS		L/SIGHTS				

FROM:

PARKER, CECIL P
RR 3 BOX 3415
TRINITY

TX 75862

SHIP TO:

PARKER, CECIL P
RR 3 BOX 3415
TRINITY

TX
75862

CUST NO: 206607 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER W/C 230145	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW			EXCISE		
☐ LIGHTLY WORN			TAX		
☐ WORN			INSURANCE		
☐ VERY WORN			UPS		
☐ UNREPAIRABLE			PARCEL POST		
☐ MARRED			TOTAL ☐ <i>W/C</i>		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Adjustments Altered to unsafe condition,
FC sluggish from sticky, gummy residue
AS Received bolt release was stuck - had to be moved
with screwdriver because of the sticky residue*

RTS

*Per phone conversation
3/5/99*

COMMENTS

*Send owners Manual
(2) Put in New FC w/c*

*(FC from this gun held by)
product service in
Ammo Cabinet #5*

FLS 3/5/99

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/97

2-19-99

REMINGTON ARMS CO
14- HOESLER AVE
ITHACA, NY. 14857

MR. FRED SUPRY:

I AM SENDING YOU
THE 270-RIFLE I SPOKE TO YOU ABOUT

AS TO WHAT HAPPENED:

ON JAN-3-1999 I WAS HUNTING OUT
OF A BOX BLIND WITH WEATHER 22%
WHEN I LOADED THE RIFLE WITH THE
BARREL POINTED OUT THE SIDE WINDOW
AND THE BUTT OF THE GUN IN MY LAP
WHEN I CLOSED THE BOLT AND WENT
TO PUT IN ON SAFE THE GUN FIRED WITH
~~THE~~ THE IMPACT HITTING ME IN THE
MUSCLE OF THE RIGHT LEG. I HAD TO BE
PUT IN THE HOSPITAL FOR 3 WKS AND STILL
HAVE A STIFF LEG DR. OR SAYING MAYBE
3 TO 4 MONTHS OR LONGER. I HAVE NEVER
HAD ANY TROUBLE WITH THIS RIFLE BEFORE
NOW I AM GUN SHY.

CECIL P. PARKER
RR. 3- BOX 3413
TRINITY, TX 75862

PHONE 409-594-7336
DAY OR NIGHT.