

File Number:	11484	Arms Service number:	9909650
Last Name:	PILCHER	First Name:	STAN
Street:	38415 COUNTY RD FF	City:	AKRON
State:	CO	Zip:	80720
Work Ph:		Home Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1008		
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ
			UNI-UNC UND J
Settlement Detail:	REPLACE TRIG ASSEM UNDER UPDATE PRO		Settlement Amount:
			\$50.0
Date Opened Rem:	04/15/1999	Date Opened by P/S:	04/15/1999
		Caliber:	243
Date of Incident:		Date Closed:	04/16/1999
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	600	Serial:	A6539138
		Date Code:	XO
Date Mfgd:	12/01/1977		
RAMAC:	600	Litigation:	☐
		PreLitigation:	☐
Obsolete:	☒		
Custody:		Comments:	
Time of Modification:	8:33:11 AM	Date of Modification:	04/16/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-09650

CUSTOMER ORDER NO.

W/TERMINATOR THUMBHOLE STOCK

P.S.

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/14/99	04/15/99	XQ 12-77	A6539138		600 243 MOHAWK
ACCESSORIES		SCOPE BASE		L/SIGHTS	

FROM:

SHIP TO:

PILCHER STAN
38415 COUNTY RD FF
AKRON

CO 80720

PILCHER STAN
38415 COUNTY RD FF
AKRON

CO
80720

CUST NO: 208610 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

2071501

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Upon receipt we could not duplicate the reported concern
The rifle has not been updated - all 3 adj screws
have been set*

PARTS

91469

COMMENTS

*Explain the complaint
Trigger screws at no change*

1008
4006

4040

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 79

Dear sir

(1) The 600 Remington
has fired twice (separate
events) when the bolt
was closed on a live
cartridge. Other times
the safety would not go
off or when it was
off the trigger couldn't
be pulled. I called
Remington and they
said to send it in
it was on recall.

Please fix problem.

Set trigger pull at
2 to 3 lbs.