

File Number:	11114	Arms Service number:	9627830
Last Name:	SCHWENTKER	First Name:	C E
Street:	26 MILKY WAY DRIVE	City:	SAINT CHARLES
State:	MO	Zip:	63304
Home Ph:		Home Ph:	314-447-4056
Work Ph:		Product Type:	F A T O
Type Concern:	S	PI PD P S C:	
Concern:	F I R E D O N B O L T O P E N I N G		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UNJ UNJ UNC UND U
Settlement Detail:	REPAIR AT SPECIAL PRICE	Settlement Amount:	30.00
Date Opened Rem:	12/22/1998	Date Opened by P/S:	01/12/1999
Date of Incident:		Date Closed:	01/12/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	86562308
RAMAC:	700	Litigation:	
Custody:		Prelitigation:	
		AE	03/01/1984
		Caliber:	30-06
		Bullet Weight:	
		Manufacturer:	REM
		Date Mfgd:	03/01/1984
		Obsolete:	<input type="checkbox"/>
		The trigger screw was backed out about 1/4". Adjustments altered to an unsafe condition. Replace F.C. at special price.	
Time of Modification:	12:54:57 PM	Date of Modification:	01/12/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 98-27830

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/18/98

12/22/98

AE 3-84

B6562308

700 30-06

BDL

ACCESSORIES

L/STUDS

FROM:

SHIP TO:

SCHWENTKER C.E.
26 MILKY WAY DR.
SAINT CHARLES

MO 63304

SCHWENTKER C.E.
26 MILKY WAY DR.
SAINT CHARLESMO
63304

CUST NO: 200880 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

*Product
Service*

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Adjustments Altered to Unsafe Condition
Trigger Screw Broken out 1/4 inch*

PARTS

COMMENTS

*Replace FA at Special price
Fes 1/12/99*

REPAIRMAN

CC

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE


DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97



December 7, 1998

Remington

Dear Management,

I am writing in regards to the Remington 700 gun (serial #B6562308) that I had repaired at F&D Guns and Bluing, Inc. on January 12, 1995. The trigger assembly was replaced. Opening the bolt it will fire some times, but bolt will jam when you try to unload gun. The gun went off and put a hole in the camper shell on my truck and busted the window prior to having the trigger housing replaced. Since replacement of trigger assembly, it has went off several times when trying to unload gun. If you have any questions please give me a call (314) 447-4056. I would greatly appreciate notification upon receipt of this letter.

I am very displeased with the operation of this gun. It is unsafe and someone could get seriously hurt if they were in the way if this gun goes off accidentally. I am glad no one did get hurt.

Sincerely,

Clarence Schwentker

F&D GUNS and BLUING, INC.
5140 WESTWOOD DRIVE
HARVESTER, MO 63304
(314) 441-5897

REPAIRS COMPLETED NOTIFICATION

Sir;

Your merchandise is ready to go. We've completed the work as discussed and wanted to let you know ASAP. Please bring your Claim Check when calling for this merchandise.

☒ First Notice 4,26,95

☐ Second Notice 1-1

Ticket# 552466 Amount \$ 899⁰¹ Mfr. REMINGTON