

File Number:	11201	Arms Service number:	5902470
Last Name:	SCHULTZ	First Name:	MIKE
Street:	N 8515 PARKVIEW LANE	City:	SPOKANE
State:	WA	Zip:	99205
Home Ph:		Home Ph:	509-328-1905
Work Ph:		Product Type:	F F A T O
Type Concern:	S	PI PD P S C	Concern Code:
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND J
Settlement Detail:	REPLACE FC AND REPAIR AT NORMAL CHARG		Settlement Amount:
Date Opened Rep:	01/26/1999	Date Opened by P/S:	01/27/1999
Date of Incident:		Date Closed:	01/29/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	5382334
RAMAC:	700	Litigation:	
Custody:		Preligation:	
		Comments:	Altered adjustments - could not duplicate customers concern - Replace FC and make any other needed repairs at normal charges
Time of Modification:	8:52:57 AM	Date of Modification:	01/29/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER

R 99-02470

INITIAL CUSTOMER ORDER NO.

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/19/99

01/26/99

ET 10-70

6382334

700 300WIN

SS/MAG/BDL

ACCESSORIES

W/STUDS

FROM:

SCHULTZ, MIKE
N 6515 PARKVIEW LANE
SPOKANE

WA 99205

SHIP TO:

SCHULTZ, MIKE
N 6515 PARKVIEW LANE
SPOKANE

WA

99205

CUST NO: 204157 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

1-27

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D1

METAL

C2

D2

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

*Altered Adjustments
Could not duplicate concern*

PARTS

COMMENTS

*Replace PC make other
repairs as needed at normal charges
1/29/99*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Remington Arms Services — 1-14-99 —
Attn: Consumer Repairs 14 Hoefler Ave. ILION NY 1335;
Remington mod 700 ser # 6382384

I bought this rifle in the 1970s new
from a gun dealer in Walla Walla WA
I have not shot it more than about
40 times

When the safety is moved from
"S" to "F" the gun fires without
touching the trigger. This unwanted
discharge has occurred twice.

Please help with this unsafe
situation! I understand that there was
a recall for this problem at one time.

Thank you

Mike Schultz

Mike Schultz
N. 6515 Parkview Lane
Spokane, WA 99205
Phone or Fax 509-328-1805

P.S.

Please call me with a quote
on any charges