

File Number:	11740		Arms Service number:	9915226	
Last Name:	SPORTS OUTFITTERS INC		First Name:		
Street:	5717 16TH AVE SW		City:	CEDAR RAPIDS	
State:	IA	Zip:	52404	Home Ph:	319-396-3409
Work Ph:	319-396-9434	Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SANITA	Classification:	UND	UNJ UNC UND	
Settlement Detail:	REPLACE FIRE CONTROL AT SPECIAL PRICE			Settlement Amount:	\$0.00
Date Opened Rem:	8/6/99	Date Opened by P/S:	8/17/99	Caliber:	22-250
Date of Incident:		Date Closed:	8/18/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	C6624014	Date Code:	BL
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
		Obsolete:	☐		
Custody:		Comments:	Claim could not be duplicated. All three adjustments had been altered. Replace fire control at special price.		
Time of Modification:	8:54:37 AM	Date of Modification:	8/18/99		

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product Service*ORDER
R99-15228

INITIAL CUSTOMER ORDER NO.

DJU

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

08/04/99

08/06/99

BL 1/91

C6624014

700

22-250

VARMIT

ACCESSORIES

L/WOOD

L/FOLLOWER

L/MAG SPRING

FROM:

SPORTS OUTFITTERS INC
5717 16TH AVE SW
CEDAR RAPIDS IA 52404

SHIP TO:

SPORTS OUTFITTERS INC
5717 16TH AVE SW
CEDAR RAPIDS IA 52404

CUST NO: 001735 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE 35.00

EXCISE

TAX

INSURANCE

UPS 8.00

PARCEL POST

TOTAL 43.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt the above concern could not be duplicated.
However, we did find out 3 trigger adjustment screws have been
set and a point check adjustment has been applied.

PARTS

COMMENTS

#26345

1008
AOCReplace the complete trigger assembly
at 1/2 the normal cost

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Remington Arms Company, Inc. Repair Instructions

Print and complete this form and mail it, along with your firearm to:

Remington Arms Company, Inc.
Attn: Arms Service
14 Hoefer Avenue
Ilion, New York 13357

Name: Sports Outfitters Inc Model: 700
Address: 5717 16th Ave SW Serial #: C6624014
City: Cedar Rapids Date of Purchase: 7/22/99
State: IA Zip: 52404 (if available, please attach a copy
Telephone: (Day) (319) - 396-9434 of the proof of purchase.)
(Night) (319) - 396-3409 Internet Request

Please describe the problem you are having with your firearm: _____

Rifle fires when bolt is closed.
Customer almost shot himself, please
repair at NO charge. Thanks.

Optional Information

Ammo Type: _____ Brand: _____

or Handload Specification _____ Bullet Weight: _____ Shot Size: _____

Reminders:

Record your serial number - it will help reference your repair.
Properly package your unloaded firearm. Do not ship in a hard case.
If you would like to order a box, please call our Parts Department:
800-243-9700, 9am-5pm, EST.
Do not send live/loaded ammunition with your firearm.
Remove all accessories.

Back to Obtaining Repair Service

©1999-Remington Arms Company, Inc.