

File Number:	11174	Arms Service number:	9901804
Last Name:	STAUL	First Name:	GREG
Street:	2812 ROBERTSON RD	City:	SHARPSVILLE
State:	PA	Zip:	16150
Work Ph:		Home Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1007		
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT SPEC PRICE	Settlement Amount:	
Date Opened Rem:	01/08/1999	Date Opened by P/S:	01/21/1999
Caliber:	300WIN		
Date of Incident:		Date Closed:	01/22/1999
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	700	Serial:	6815245
Date Code:	XY	Date Mfgd:	12/01/1974
RAMAC:	700	Litigation:	<input type="checkbox"/>
PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>
Custody:		Comments:	
Time of Modification:	8:00:34 AM	Date of Modification:	01/23/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 99-01804

INITIAL

CUSTOMER ORDER NO.

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/08/99

01/20/99

6815245

700 300 WIN

MAG/BDL

ACCESSORIES

W/STUDS

L/ REAR SIGHT

XY 12-74 2ND TIME IN

FROM:

SHIP TO:

STAUL GREG
2812 ROBERTSON RD.
SHARPSVILLE

PA 16150

STAUL GREG
2812 ROBERTSON RD.
SHARPSVILLE

PA

16150

CUST NO: 202864 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

PROM. DATE

ESTIMATED

VIA

3293001

WRITE ☐

1/21

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☒ MARRED

* ATTN: Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

30.00

8.00

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

AS safety was moved the gun

TRIGGER GROUP

B2

DISCHARGED

E1

F1

SLT ASSY.

B3

E2

F2

BARRREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt we could not duplicate the reported concern, but did find the trigger components working sluggish from being covered with a heavy sticky substance. The trigger & stop screws have been re-set, and oiled.

#26345

1007

4006

COMMENTS

Replace the complete trigger assembly at 1/2 the normal cost.

Go ahead

REPAIRMAN

B.W.D.

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

whom it may concern,

On November 30th my daughter and I were hunting, at the end of the day when we were
loading our rifles the rifle my daughter was using was a Remington model 700 BDL in the
Winchester magnum caliber serial number 6815245. She began by opening the magazine door,
moving the cartridges in the magazine, then moving the safety to the fire position to
unload the gun. As the safety was moved the gun discharged, I have tried several times
the rifle to fire coming off of safety but the safety has worked proper. My daughter told me
she absolutely did not touch the trigger. Myself and Remington felt the rifle should be
checked by a qualified gun smith

Thank You Gregory A. Staul
2812 Robinson Rd.
Sharpsville Pa. 16150

telephone 724-962-7195

Remington 700 BDL 300 Win. Magnum
serial number 6815245