

File Number:	11314	Arms Service number:	9905185
Last Name:	STRAIN	First Name:	CHARLES
Street:	716 GREEN FOREST RD	City:	RIDGELAND
State:	MS	Zip:	39157
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F A T
Concern Code:	PI PD P S	Concern Code:	1020
Concern:	FIRED ON BOLT OPENING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNI UNC UND
Settlement Detail:	REPAIR AT SPEC PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	02/22/1999	Date Opened by P/S:	02/26/1999
Date of Incident:		Date Closed:	02/26/1999
Date to Analysis:		Bullet Weight:	
Date from Analysis:		Manufacturer:	REM
Model:	721	Serial:	200865
RAMAC:	721	Date Code:	DXX
Litigation:	☐	Date Mfgd:	09/01/1951
PreLitigation:	☐	Obsolete:	☒
Custody:		Comments:	
Time of Modification:	1:02:42 PM	Date of Modification:	02/26/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

product
serviceORDER
R 99-05185INITIAL
PS

CUSTOMER ORDER NO.

DATE RECEIVED

02/15/99

DATE OPENED

02/22/99

DATE CODE

DXX9-51

SERIAL NUMBER

200864

NEW SERIAL NUMBER

MODEL AND GRADE

721 30-06

ACCESSORIES

SCOPE BASE

W/RECOIL PAD

FROM:

STRAIN, CHARLES R.
716 GREEN FOREST RD
RIDGELAND

MS 39157

SHIP TO:

STRAIN, CHARLES R.
716 GREEN FOREST RD
RIDGELANDMS
39157

CUST NO: 204236 C.O.D.

ACCOUNT NUMBER

2293001

ACCOUNT NUMBER N/C

WRITE



PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

30.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD				D3	E5	F5
METAL						

MAIN FAULT

My 1951 We could not duplicate the Customer Concern,
but did find the action & trigger assembly dirty, and the
only remedy was clean & set

PARTS

COMMENTS

Replace the compact
trigger assembly at spec price

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

TO WHOM IT MAY CONCERN:

THE ENCLOSED REMINGTON MODEL 721
30/06 WAS TWICE DISCHARGED DURING
UNLOADING WHEN THE BOLT HANDLE WAS
PUSHED DOWN INTO THE LOCKED POSITION.
IN NEITHER CASE WAS THERE ANY POSSIBILITY
THAT ANYTHING WAS IN CONTACT WITH
THE TRIGGER.

PLEASE REPAIR AND RETURN TO:

CHARLES R. STRAIN
716 GREEN FOREST RD
RIDGELAND, MS
39157

TEL. NO. (601) 956-8929

THANKS,

Charles R. Strain