


File Number:	12693		Arms Service number:	00000327	
Last Name:	TACKLE SHACK		First Name:		
Street:	1350 S MARKET STREET		City:	TROY	
State:	OH	Zip:	45373	Home Ph:	
Work Ph:		Product Type:	F A T		
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SANITA	Classification:	UNJ	UNJ UNC UND	
Settlement Detail:	REPAIR AT SPEC PRICE		Settlement Amount:	\$0.00	
Date Opened Rem:	12/15/99	Date Opened by P/S:	12/15/99	Caliber:	50
Date of Incident:		Date Closed:	12/16/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700ML	Serial:	ML042681	Date Code:	
RAMAC:	700ML	Litigation:	☐	PreLitigation:	☐
		Obsolete:	☐		
Custody:		Comments:	RIFLE POORLY MAINTAINED		
Time of Modification:	1:24:54 PM		Date of Modification:	12/16/99	

Serial Number: ML042681

Model ID: 700 MLS



RE00000327

Change Repair

12/16/19

Fuel when bolt is checked

*1008
4015*

*Living pin & trigger pin rusty. Rifle
not cleaned properly.*

*Repair the complete trigger assembly & living pin
at special price 1/2 the normal cost*

*48.00
8.00
56.00*

Smith

Serial Number: ML042681

Model ID: 700 MLS



RE00000327

CUSTOMER SAID AFTER SHOOTING
SATURDAY, HE CLEANED THE GUN AND AFTER-
WARDS THE GUN WOULD FIRE WHEN THE
BOLT WAS CLOSED, ALSO IS THE
SAFETY SET WHEN THE BOLT IS OPENED?

SERIAL NUMBER

ML042681

RETURN TO:

TACKLE SHACK

1350 S MARKET

TROY, OH 45373

PHONE NUMBER

1-937-339-4455

FAX 1-937-332-0074

THANK YOU!

A. J. Anderson