

File Number:	11278	Arms Service number:	9904111
Last Name:	WOODHAVEN RIFLE & PISTOL RAN	First Name:	D SPALLONE
Street:	74-16 JAMAICA AVE	City:	WOODHAVEN
State:	NY	Zip:	11421
Home Ph:		Home Ph:	
Work Ph:		Product Type:	F F A T O
Type Concern:	S P I P S C	Concern Code:	1026
Concern:	FIRED WITH SAFE ON		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UND UNJ LNC UND J
Settlement Detail:	REPLACE FC AND CHECK FUNCTION		
Date Opened Rem:	02/10/1999	Date Opened by P/S:	02/16/1999
Date of Incident:		Date Closed:	02/17/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	A6276060
RAMAC:	700	Litigation:	
Custody:		Prelitigation:	
		Chslets:	
		Manufacturer:	REM
		Date Mfgd:	03/01/1978
		Caliber:	30-06
		Bullet Weight:	
		Settlement Amount:	\$50.00
		Comments:	Model 700 FC had altered adjustments, rust, and build up of residue. Replace FC at 1/2 normal price and check gun over for heavy bolt lift
Time of Modification:	11:53:23 AM	Date of Modification:	02/17/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

IN HARD
CASEORDER
R 99-04111INITIAL
RLP

CUSTOMER ORDER NO.

W/TASCO 3X-9X40 SCOPE

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

HARD CASE

SCOPE MNTS

SCOPE BASE

700 30-06

Product
SERVICE
ADL

FROM:

SHIP TO:

WOODHAVEN RIFEL & PISTOL
RANGE INC ATTN D SPALLONE
74-16 JAMAICA AVE
WOODHAVEN NY 11421WOODHAVEN RIFEL & PISTOL
RANGE INC ATTN D SPALLONE
74-16 JAMAICA AVE
WOODHAVEN NY 11421

CUST NO: 022626 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

FROM DATE

ESTIMATED

VIA

2293001

WRITE ☐

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt we could not duplicate the firing when cocked down,
but did find that the trigger was not set, the trigger
assembly is dirty, just needing cleaning. This is easily done
on the bench & action. Check for hard spring.

PARTS

COMMENTS

#26345

Replace the trigger
assembly at 1/2 the normal cost \$30.00.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

C.R.

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

WOODHAVEN RIFLE & PISTOL RANGE INC.
SPORTING GOODS AND EQUIPMENT
74-16 JAMAICA AVENUE
WOODHAVEN, N.Y. 11421

Remington Arms Company
Ilion, New York 13357

2/1/99

Dear Sirs;

Enclosed Model 700, 30/06 Rifle, Serial #A6276010 sent to you for repair. My customer Mr. Bholam Rajnarain finds that the bolt seizes after firing a few rounds. Also with the rifle in safety position any movement and the rifle when cocked will discharge.

Sent with Tasco 3x9 Scope
See thru Mounts
1 Hard Rifle Case - Hoppes Protecto

enc:FFL

Sincerely,



Don Spallone