

File Number:	11712		Arms Service number:	9915119	
Last Name:	SCHNEIDER		First Name:	LARRY	
Street:	3605 S COUNTY RD		City:	MIDLAND	
State:	TX	Zip:	79706	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SANITA	Classification:	UNJ	UNJ UNC UND	
Settlement Detail:	REPLACE TRIG ASSEM NEVER UPDATED			Settlement Amount:	\$0.00
Date Opened Rem:	8/4/99	Date Opened by P/S:	8/4/99	Caliber:	308
Date of Incident:		Date Closed:	8/5/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REN
Model:	600	Serial:	6532779	Date Code:	AX
Date Mfgd:	3/1/73				
RAMAC:	600	Litigation:	☐	PreLitigation:	☐
Obsolete:	☒				
Custody:		Comments:			
Time of Modification:	9:02:38 AM		Date of Modification:	8/5/99	

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R99-15119

INITIAL

CUSTOMER ORDER NO.

PSP

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

08/02/99

08/04/99

AX 3/73

6532779

600 308

MOHAWK

ACCESSORIES

L/SIGHTS

FROM:

SHIP TO:

SCHNEIDER LARRY
3605 SOUTH COUNTY RD. 1184
MIDLAND TX 79706

SCHNEIDER LARRY
3605 SOUTH COUNTY RD. 1184
MIDLAND TX
79706

CUST NO: 212337 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

BOLT ASSY.

B3

E2

BARREL ASSY.

B4

D1

E3

REC. ASSY.

B5

D2

E4

WOOD

C1

D3

E5

METAL

C2

F5

MAIN FAULT

Update 1973 has not been updated. Upon receipt we could not duplicate the reported concern. However, we did find the old repair has been tampered with.

PARTS

COMMENTS

91649

Repair the complete trigger
assembly per Update procedure
at no charge

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Larry Schneider

3605 South County Road 1184

Midland, Texas 79706

Phone 915-684-4860

Here is The Remington Mohawk 200
we talked about on the phone, it has the gold trigger
we talked about, the firing pin fails when I close
the bolt. I cleaned the trigger with a spray solvent
as you said, it didn't help. you said it could be a defect
in the model 600 Rifle. Please let me know if you
can fix it.

P.S. There is a screw broke off front sight, please remove
~~front~~ broke screw.

Thanks

Larry Schneider