

\$20 Remington® Brand

SAFETY REBATE

Receive up to
\$20 Rebate back
from Remington for the
purchase of any of the
following items. Multiple
purchases at one time
may be made to
receive full
\$20 rebate.

Please retain for your records - Important information on back



Any Remington Safe

Premier Series
Classic Series
"E" Series (Electronic Lock)
Sportsman Series
Express Gun Cabinet
Trophy Series



Remington Ear Muffs

Models M-24, M-28,
Rangemaster Eye/Ear Protection,
M-31, Safety Combo Pack and
R2000 Electronic Hearing Protection
(Note: Plugs not included)



Remington Brand Safety Glasses

Sportsmaster II Shooting Glasses
Sportsmaster Shooting Glasses
422 Series
Premier
Clip-On/Flip-Up Shooting Glasses



Remington Locking Devices

Trigger Block (Single or Three Pack)
Cable Lock

To get your rebate, complete this form and enclose the original cash register receipt showing the store name and price you paid - Along with the UPC codes from the item(s). For safes please provide serial number _____

I purchased _____ (Qty) Remington _____ Model # _____

Send my \$20 Rebate.

Store Name _____

First Name _____ Last Name _____

Street _____ P.O.Box _____

City _____ State _____ Zip _____

E-mail Address _____

(If you would like to receive news of additional offers from Remington)

Warranty Center Name _____

Model # _____ Serial # _____

Mail to:

Remington Safety Offer Rebate

1407 Airport Road

Suite 2247

Monroe, NC 28110

Offer good on purchases made between Mar. 1, 2002 and Dec. 31, 2002.

Requests must be received by Jan. 31, 2003. Allow 8 weeks for delivery.

Offer void if coupon, cash register receipt or proof of purchase are reproduced

Offer void where prohibited, taxed or restricted by law. Offer good only in US

Call 1-800-432-5807 for inquiries regarding the status of your rebate.

Warranty Center #

R 2202717

IMPORTANT SAFETY MESSAGE

FOR OWNERS OF CERTAIN REMINGTON® BOLT-ACTION CENTERFIRE FIREARMS MANUFACTURED BEFORE 1982

The Remington® Arms Company, Inc. is offering a **safety modification program** for certain bolt-action centerfire firearms manufactured prior to 1982, including the Model 700™ (made before March 1982), Model 600™, 660™, 721™, 722™, 40-X bolt-action rifles, and Model XP-100 target pistols (made before February 1975). These firearms have a feature known as a bolt-lock that requires the safety to be placed in the "off" position in order to unload the gun. If you participate in this program, your firearm will be modified to eliminate the bolt-lock feature. The operation of your gun will not be otherwise affected.

Why is Remington offering this safety modification program? A "bolt-lock" locks a firearm's bolt in the "down" or "ready-to-fire" position whenever the manual safety is in the "on" or "safe" position. Traditionally, the purpose of the feature was to prevent inadvertent lifting of the bolt while a rifle is being carried in the field. Users of these firearms need to be particularly cautious when unloading, however, because the safety must be in the "off" or "fire" position to raise the bolt and begin the unloading process. Remington is aware of reports that rifles with this feature have accidentally discharged while being unloaded, and whenever a gun fires accidentally, there is a risk of property damage, serious injury or death. This program is for owners of older bolt-action firearms who want to be able to unload their guns with the manual safety in the "on" or "safe" position.

What is the cost of this modification? For all rifles except certain Model 600's, 660's and some Model XP-100 target pistols, you will be charged \$20 for cleaning, inspection and removal of the bolt-lock, plus shipping and handling. If you participate in this bolt-lock removal program, you will also receive a transferable coupon good for up to \$20 towards the purchase of any Remington safety product, including gun locks, hearing and eye protection, and gun safes.

What about Model 600 and 660 rifles? Most Model 600 and 660 rifles (plus some XP-100's) were recalled and repaired in 1979 for safety reasons related to the trigger assembly. Model 600 and 660 rifles were manufactured (or retrofitted) with bolt-lock features. If your rifle was not retrofitted as part of that recall, the entire trigger assembly will be replaced at no charge. To check whether your Model 600 or 660 rifle, or Model XP-100, was subject to the 1979 recall or repaired as part of it, call Remington toll-free at 877-387-6691 with the serial number of your gun. To learn more about the 1979 safety recall, check our website at www.remington.com.

What to do to have your bolt-lock rifle modified? If you own one of these older rifles and want to participate in this safety program, or if you want assistance in determining whether your bolt-action centerfire gun is equipped with a bolt-lock, call Remington's toll-free consumer hotline at 877-387-6691 or visit our website at www.remington.com.

REMEMBER: Whether or not your rifle has a bolt-lock feature, you must always follow the 10 Commandments of Safety. In particular, always keep the muzzle of your gun pointed in a safe direction, especially when you're loading or unloading. And always unload your gun when not actually in use. Every firearm should be unloaded as soon as you are finished shooting — before taking it into your car, camp or home. Remington wants you to enjoy the shooting sports — safely!

Offer valid through December 31, 2002.

Remington®

870 Remington Drive | Madison, North Carolina 27025-0700 | www.remington.com

To: All Remington Arms Repair Centers
From: Remington Arms – Field Service

Date: 25 February 2002

Please review the attached instructions with your gunsmiths. Remington is going to release via sporting magazines an offer to clean, inspect, and remove the bolt lock from our line of bolt action rifles that were equipped with the bolt lock feature. This will be voluntary for the customer. The packet explains our offer. We wanted you to be aware of this prior to it being released to the general public. One of our field service representatives will be contacting you to discuss the enclosed documents and our offer.

If you have questions or are contacted by customers with questions about this offer please refer to our web site www.remington.com for additional information.

List of Attachments:

1. Copy of message being sent to magazines, and a list of magazines that the message will be published in.
2. Bolt Lock update program flow chart for Model 600, 660, 700, 40-X, and XP-100.
3. Procedure for changing bolt lock to non-bolt lock for Model 600, 660, 700, 40-X, and XP-100 – 3 pages.
4. Bolt Lock update program flow chart for Model 721 and 722.
5. Procedure for changing bolt lock to non-bolt lock for Model 721 and 722 – 3 pages.
6. Copies of the Bolt Lock update modification program as shown on our web site – 9 pages.
7. Labor Reimbursement schedule.
8. Repair packet containing:
 - Trigger Assembly Checklist
 - Change of operation notice
 - Decline of Repair Form
 - Safety Rebate Coupon with firearm care instructions.

Bolt Lock Update Program
Model 700, 600, 660 xp-100, 40-x

Walks into Gunsmith



Determine model and
year of manufacture



Review options
with consumer and
obtain direction from them



Review firearm
Complete trigger assembly
checklist.



Discuss options with
consumer based on review of
firearms



Proceed with repair per
instructions from consumer



Charge according to
reimbursement schedule



Return gun to consumer

if firearm is in unsafe
condition and customer denies
service have denial of service
completed



Complete Paperwork
- warranty form
- Trigger assembly Checklist
- Denial of Service
and send to Remington

Options

700, XP-100, 40-X,

- Clean and inspect and ...removal
- Clean and inspect and bolt lock removal
- Fire control replacement

600, 660

- if already recalled
 - Clean and inspect and ...removal
 - Clean and inspect and bolt lock removal
 - Fire control replacement
- If never recalled - New fire control without bolt lock feature