

Models 700, XP-100 and 40-X

	Clean and Inspect	Clean, Inspect and Bolt lock feature Removal	Fire control Replacement
Consumer payment to warranty center	\$20	\$20	\$20
Remington Arms Co., Inc. payment to warranty center	\$10	\$20	\$20
Paper Work to Consumer	1. Coupon 2. Denial of Update – get back from customer	1. Coupon 2. Notice of Operation	1. Coupon 2. Notice of Operation

Models 721 & 722

	Clean and Inspect	Clean, Inspect and Bolt lock feature Removal	Fire control Replacement
Consumer payment to warranty center	\$20	\$20	N/A
Remington Arms Co., Inc. payment to warranty center	\$10	\$20	N/A
Paper work to Consumer	1. Coupon 2. Denial of Update – get back from customer	1. Coupon 2. Notice of Operation	Notify that gun has been sent back to factory

Model 600 and 660

	Clean and Inspect	Clean, Inspect and Bolt lock feature Removal	Fire control replacement due to maintenance	Fire control Replacement due to recall
Consumer payment to warranty center	\$20	\$20	\$20	Free
Remington Arms Co., Inc. payment to warranty center	\$10	\$20	\$20	\$40
Paper work to Consumer	1. Coupon 2. Denial of Update – get back from customer	1. Coupon 2. Notice of Operation	1. Coupon 2. Notice of Operation	1. Coupon 2. Notice of Operation