

DATE

9-20-44

SUBJECT OF EXPT.

M-722 Preliminary Tests

360 preliminary rounds through the m-722 gave one failure to feed due to the cartridge base ducking under the bolt. The bolt on the m-722 is noticeably hard on closing due to the extractor. A few of these 360 were fired at the target with very good results.

EXPERIMENTER:

DATE

WITNESS

DATE