

DATE

9-21-44

SUBJECT OF EXPT.

M-721 Preliminary tests.

After proofing the M-721 had .004" excess head space (.227"). Max heading on assembly and poor contact on the lips contributed to this condition.

EXPERIMENTER

WITNESS

DATE

DATE