

Noted

Copies to: Messrs. C. K. Davis
 D. F. Carpenter
 W. O. Reisinger
 B. E. Strader
 E. L. Bertland
 E. C. Griffing
 F. J. Craig
 G. O. Clifford
 M. E. Warden (2)
 G. E. Pinckney
 C. C. Mitchell
 W. L. Clay
 Bridgeport, Conn.

A. R. Dorr
 A. L. Lowe
 W. H. Davis
 G. R. McCormick
 R. H. Grace
 E. A. Walsh
 C. W. Borden (5)
 P. E. Rutherford
 D. E. Miller
 S. W. Rose
 R. J. Seiler
 R. A. Williamson
 R. A. Hentschel
 A. J. Borden

CUSTOMERS' COMPLAINTS ON FIREARMS FOR MONTH ENDED JAN. 31, 1946

	PRODUCED WITHIN ONE YEAR	TOTAL
<u>Model 81</u>		
Indicator broken.	1	1
O Don't lock back.		1
O Shells jump magazine.		1
O Jacket head loose.	1	1
Seam in barrel.		1
Extractor broken.	1	1
X Front sight base to left.	1	1
O Magazine out of adjustment.		1
	<u>4</u>	<u>8</u>
<u>Sportsman 12 Ga.</u>		
O Stock checked.	3	3
X Take down screw binds.	<u>1</u>	<u>1</u>
	4	4
<u>Model 11 12 Ga.</u>		
Trigger spring broken.	1	1
Seam in barrel.	1	1
O Receiver cushion broken.	<u>2</u>	<u>2</u>
	4	4
<u>Model 121</u>		
O Fails to eject.	1	1
Firing pin broken.	1	2
O Don't lock up.	2	2
O Fails to feed.	2	2
X Opens hard on full magazine.	<u>1</u>	<u>1</u>
	7	8
<u>Model 141</u>		
O Fails to feed.	2	2
O Stock checked.	<u>1</u>	<u>1</u>
	3	3
<u>Model 241</u>		
O Shells jump cartridge stop	1	1
X Trigger guard loose in receiver.	2	2
Firing pin broken.		1
O Does not disconnect.	2	2
O Does not cock.	1	1
X Barrel loose. Take-up gone.	<u>4</u>	<u>4</u>
	10	11
<u>Model 720</u>		
X Bolt key lug long.		1
O Misfire.		<u>1</u>

CUSTOMERS' COMPLAINTS ON FIREARMS FOR MONTH ENDED JAN. 31, 1946

	PRODUCED WITHIN ONE YEAR	TOTAL
<u>Model 31 12 GA.</u>		
Right extractor broken.	1	1
Action bar broken (old style)		1
O Cartridge stop out of adjustment.	$\frac{1}{2}$	$\frac{1}{3}$
<u>Model 510</u>		
O Jar off.	2	2
Sear pivot broken.	1	1
bolt broken extractor slot.	1	1
X Misfire - strike inside.	1	1
O Fails to eject.	1	1
X Defective chamber.	$\frac{1}{7}$	$\frac{1}{7}$
<u>Model 511</u>		
Magazine lock broken.	2	2
O Jar off.	1	1
Bolt handle broken.	1	1
O Misfire.	$\frac{1}{5}$	$\frac{1}{5}$
<u>Model 512</u>		
X Shells slip by cartridge retainer.	4	4
O Fails to eject.	4	4
O Fails to feed.	4	4
X Not accurate.	2	2
X Carrier & trigger bind.	1	1
O Misfire.	2	2
Sear broken.	2	2
X Defective chamber.	1	1
O Jar off.	$\frac{1}{21}$	$\frac{1}{21}$
<u>Model 513</u>		
Bolt handle broken.	2	2
O Misfire.	1	1
X Not properly bedded.	$\frac{1}{4}$	$\frac{1}{4}$
<u>Model 550</u>		
O Don't cock.		2
O Fails to eject.		12
O Misfire.		$\frac{1}{15}$
		15
	TOTAL	95

Corrected in recent production.

X Oversight in inspection.

O Close adjustment not showing up in factory tests,
resulting in malfunction through usage.

Total for January, 1946	95
Total for January, 1945	21
Grand total to date, 1946.....	95
Grand total to date, 1945.....	21
Grand total Feb. 1, 1945, to Jan. 31, 1946.....	357
Grand total Feb. 1, 1944, to Jan. 31, 1945.....	262
Last 12 months running average.....	29
12 months running average (one year ago).....	22
12 Months running average (six months ago)	18
Produced within one year.....	71
Produced within one year (six months ago).....	0
Produced within one year (one year ago).....	0
Produced within one year (two years ago).....	0

S. W. rose/mcD.
February 5, 1946.