Copies to: Messrs. C. K. Davis
D. F. Carpenter
W. O. Reisinger
B. B. Strader A. R. Dorr A. L. Lowe W. H. Davis G. R. McCormick E. C. Griffing F. J. Craig G. O. Clifford R. H. Grace -E. A. Walsh C. W. Borden (5) P. B. Rutherford M. E. marden (2) G. B. Pinckney D. B. Miller A. L. French S. W. Rose H. L. Clay R. J. Seiler R. A. Williamson Bridgeport, Conn. A. J. Borden

CUSTOMERS! COMPLAINTS ON FIREARMS FOR MONTH ENDED APRIL 30, 1946

	PRODUCED WITHIN ONE YEAR	TOTAL
Model 81 O Jacket head loose.	,	1
Extractor broken.		ī
X Front sight base to left.	1	Ţ
O Stock checked. Barrel lock broken.	. 1	ļ
X Magazine follower binds.	1	ī 1
O Can not pull trigger.	_	ĩ
I Take down screw doesn't qualify.	<u>.</u>	
Sportsman 12 ga.	•	•
O Stock checked.	1	1
Extractor pin broken.	$-\frac{1}{2}$	- 1/2
Model 11 12 gs.		•
O Stock checked. O Carrier latch out of adjustment.	3 1	3 1 1
Breech block broken.	ī	ī
O Rusty barrel outside.	-]	- ,
Nodel 121	•	
Firing oin broken.	ļ	Ţ
O fails to feed - feeds hard. O Takes maximum plug.	4	4
X Extractor hole in block too larg	e1	1 4 1 -7
	<u> </u>	7
<u>Model 141</u> O Cartridge jumps stop.	1	3
	1	1
Nodel 241 O Does not disconnect.	2 .	2
I Barrel take down loose.	3	- 3
X Poor crown on barrel.	į	1
X Disconnector short.	3 3 1 -1	3 1 1 8
Model 31 12 ge.	•	•
X Bad spot inside barrel.		1
Model 31 20 ga.	Τ.	
O Stock checked.	1	ı
X Fails to feed properly.		<u> </u>
	~	4

	PRODUCED WITHIN	TOTAL
<u>Model 510</u> 0 Jar off.		1
O Fails to eject.	<u>1</u>	1/2
Model 511 Magazine lock broken.	1	1
O Jar off. O Misfire.	1 2 1 2 1	2
X Not accurate.	2	2
O fails to eject. Sear broken.	1 1 8	1 2 1 2 1 1
Model 512 O Fails to eject.	. 1	1
O Fails to feed.	1 3 1 3 3 1 1	1 3 1 3 1 1
X Not accurate. OnRetainer out of adjustment.	1 3	1 3
O'Misfire.	<u>3</u> 1	ĺ
Broken sear. Bolt sleeve broken.	1	3 · · · · · · · · · · · · · · · · · · ·
O Pulls off on safe.	į	ļ
X Tear in bore of barrel. Ejector broken.	1 16	$\frac{1}{16}$
Wodel 513 Bolt handle broken.	•	1
O fails to extract.	$-\frac{1}{2}$	$-\frac{1}{2}$
Model 550 O Fails to eject.		13
O Catch in insert.	•	2
Cartridge stop broken. O Extractor out of adjustment.		6
0 Action spring weak.		13 2 1 6 <u>1</u> 23
TOTAL	57	86

[#] Corrected in recent production
X Oversight in inspection.
O close adjustment not showing up in factory tests,
resulting in malfunction through usage.

CUSTOMERS! COMPLAINTS ON FIREARMS FOR MONTH ENDED APRIL 30, 1946 Total for April, 1946 Total for April, 1945 86 24 Grand total to date, 1946 372 Grand total to date, 1945 83 Grand total May 1, 1945, to April 30, 1946 Grand total May 1, 1944, to April 30, 1945 572 228 47 19 Last 12 months' running average 12 Months' running average (one year ago) 12 Months running average (six months ago) Produced within one year (six months ago) Produced within one year (one year ago) Produced within one year (two years ago) 57 17 0

8. W. Rose/McD. May 3, 1946

في المحمد