	·			
Contraction of the Contraction o	COPIES TO: MESS	D.E.CARP W.O.REIS B.E.STRA F.J.CRAI G.O.CLIF M.R.WARD G.E.PINC A.L.FREN W.L.CLAY BRIDGEP	ENTER INGER DER G FORD EN KNEY CH ORT, CONN.	H.X.FAULKNER W.H.DAVIS H.A.BROWN R.H.GRACE C.W.BORDEN (5 P.B.RUTHERFORI D.E.MILLER S.W.ROSE R.J.SEILER R.A.WILLIAMSOI A.J.BROWN S.M.A. T.B.
2		PR	ODUCED WITH	IN TOTAL
MODEL 0 Q	81 JACKET HEAD LOOSE FAILS TO EXTRACT (EXTRACTO	R OUT OF	3	li li
0	ADJUSTMENT.) MAGAZINE SIDE SPRING OUT O	•	3	3
. 0	EXTRACTOR BROKEN MAGAZINE SPRING BROKEN ACTION FAILS TO LOCK BACK		1	1
0 X	EJECTOR SPRING WEAK CHAMBER ROUGH		1	
×	FRONT SIGHT BASE MILLED WR	ONG	15	77
SPORT.	SMAN - 12 GA. CARTRIDGE STOP OUT OF ADJU	STMENT	1	1
. X	STOCK CHECKED BREECH BLOCK RAIL IN RECEI DEEP SCRATCH IN BARREL (PO EXTRACTOR CLEARANCE CUT IN	OR STRIKING)	1	9
X		BARREL TOO DE	3	5
SPORT X 0	SMAN - 16 GA. CARRIER DOG FILED OUT OF S CARTRIDGE STOP OUT OF ADJU		1	
0 0 N	FEEDS HARD UNDER EXTRACTOR TRIGGER AND HAMMER OUT OF BARREL BORED ECCENTRIC		1 2 1	i 2 1
			5	6
SPORT	SMAN - 20 GA. FORE-END LETS BARREL TOO F	ORWARD		
MODEL O N	11 - 12 GA. SHELLS STEM CHAMBER BARREL WALL THIN, ONE SIDE		1 1	1
ŭ .	THEFERRAL BALL PURPLE WHEN TO	TT AR HIGH TAR	E1 #1 1	4

SHEET NO. 1.

Tpul

		PRODUCED WITHIN ONE YEAR	TOTAL
MODEL	11 - 16 GA.		
X	EXTRACTOR FILED POORLY	1	1
X	CARRIER DOG FILED TOO MUCH	1	1
0	EXTRACTOR OUT OF ADJUSTMENT		_1_
		2	3
140051	11 00 01		
MODEL	11 - 20 GA. BARREL BINDS IN ACTION		1
U	DARKEL DIRUS IN ACTION		
		•	•
MODEL	121		•
	FIRING PINBROKEN	1	2
X	BREECH BLOCK FILED OUT OF SHAPE	<u>1</u>	. <u>1</u>
X	FIRING PIN STRIKES INSIDE	5	• 5
0	, STEMS CHAMBER	3	3
Ŏ	TAKES MAX. PLUG	4	6
¥	FAILS TO EJECT NOT ACCURATE	1	2
XOOXO	FAILS TO FEED	5	. .
ŏ	CARRIER OUT OF ADJUSTMENT		. {
Ŏ.	FAILS TO EXTRACT	1	1
X	ACTION BAR MACHINED WRONG	4	.ֈֈ
	EXTRACTOR PLUNGER BROKEN	1	1.
X	GUARD ASSEMBLES HARD IN RECEIVER	<u> </u>	
		27	30
MODEL	•h•		
MART	EJECTOR ROD HOLES OUT OF POSITION		2
^ . ,	FORE-END SPLIT	1	ي و
0	FAILS TO EJECT	i	• 1
	SEAR AND SEAR LOCK OUT OF ADJUSTMENT	1	' 1
0	SEAR AND TRIGGER OUT OF ADJUSTMENT		1
0	SHELLS STEM CHAMBERS	1	1
0	FAILS TO FEED	` <u>5</u>	5
	STOCK CHECKED	2	. 2
0	UNLOCKS HARD	2	2
0	FAILS TO EXTRACT SAFETY OUT OF ADJUSTMENT	1	7
V	EXTRACTOR BROKEN	2	2
0 .	TAKE DOWN SCREW PULLS OUT	1	ī
	CARTRIDGE STOP BROKEN	2	ż
		20	24
	-1-		
MODEL	241		
0	CARTRIDGES STICK IN CARTRIDGE GUIDE FE	EDING 1	1
0 X	FAILS TO DISCONNECT	Į.	. 4
X	TRIGGER GUARD LOOSE IN RECEIVER	j 1	٤,
^	EXTRACTOR BROKEN FAILS TO EJECT	•	1
C	SIGHTS OUT OF LINE	3	2
-	SIMILA ON AL MINE	3)

SHEET NO 2

MODEL X X	241 (CONTINUED) NOT ACCURATE (MUZZLE UPSET) CARTRIDGE STOP OUT OF ADJUSTMENT FRONT SIGHT SLOT MILLED WRONG STOCK MACHINED WRONG AT RECEIVER TRIGGER BROKEN STOCK CHECKED ACTION SPRING PLUNGER BINDS	PRODUCED WITHIN ONE YEAR 1 1 1 1 1 2 1	TOTAL
MODEL X O O	31 - 12 GA. RIB ON BARREL POOR SHAPE TRIGGER LOCK OUT OF POSITION FAILS TO EJECT CARTRIDGE STOP OUT OF ADJUSTMENT	16 1 1 1	1 1 1 1
MODEL	31 - 16 GA. STOCK CHECKED	+	+
0	STOCK CHECKED BOLT MISMATCHED TRIGGER PULL HEAVY EXTRACTOR OUT. OF ADJUSTMENT BOLT MISMATCHED	1 1 1 2	1 1 1 2
O MODEL	SLING STRAP STRETCHES TAKES MAX. PLUG	8	-18
O X O N	FAILS TO EJECT FRONT SIGHT NOT PROPERLY FITTED BOLT HANDLE LOOSE REAR SIGHT STEP TOO LOW RECEIVER INSERT BROKEN	1	1 1 1 5
MODEL	511 MAGAZINE LOCK BROKEN STOCK CHECKED	1	1
0 0 X 0 0 X X	EJECTOR OUT OF POSITION FIRING PIN FOLLOWS DOWN FIRING PIN NOTCH OUT OF POSITION RIFLE TAKES MAX. PLUG BOLT HANDLE LOOSE MAX. GUIDE PLATE OUT OF POSITION RECEIVER MILLED WRONG AT EJECTOR POR SEAR STUD BROKEN FAILS TO FEED	T 1	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

SHEET NO. 3.

2 4,		PRODUCED WITHIN ONE YEAR	TOTAL
MODEL O O O	CARTRIDGE RETAINER OUT OF ADJUSTMENT FAILS TO FEED EJECTOR TOO LOW (FAILS TO EJECT) STOCK CHECKED TAKES MAX. PLUG CARTRIDGE STOP BINDS RECEIVER INSERT BROKEN	6 2 5 2 1 2	7 36 2 1 1 2
MODEL O X X O O	FAILS TO EJECT (EJECTOR LOW) STOCK CHECKED TOOL MARK IN BARREL FRONT SIGHT SLOT IN BARREL ON ANGLE FAILS TO COCK (SEAR DAMAGED) LUG ON BOLT DAMAGED	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3
MODEL	550 RIGHT EXTRACTOR OUT OF ADJUSTMENT	1	+
MODEL	720 FRONT SIGHT TIPS		_

NOT COVERED BY INSPECTION.
CORRECTED IN RECENT PRODUCTION.
OVERSIGHT IN INSPECTION.
CLOSE ADJUSTMENT NOT SHOWING UP IN
FACTORY TESTS, RESULTING IN MALFUNCTION
THROUGH USAGE.

TOTAL FOR APRIL , 1947	172
TOTAL FOR APRIL, 1946	86
GRAND TOTAL TO DATE, 1947	570
GRAND TOTAL TO DATE, 1946	372
GRAND TOTAL MAY 1,1946 TO APRIL 30, 1947	1212
GRAND TOTAL MAY 1, 1945 TO APRIL 30, 1946	572
LAST 12 MONTHS RUNNING AVERAGE	101
12 MONTHS RUNNING AVERAGE (ONE YEAR AGO)	47
12 MONTHS RUNNING AVERAGE (SIX MONTHS AGO)	83
· •••••••	
PRODUCED WITHIN ONE YEAR	144
PRODUCED WITHIN ONE YEAR (SIX MONTHS AGO)	79
PRODUCED WITHINGNE YEAR (ONE YEAR AGO)	57
PRODUCED WITHIN ONE YEAR (TWO YEARS AGO)	O
•••••	
GRAND TOTAL GUNS PRODUCED WITHIN ONE YEAR (FROM MAY 1, 1946 TO APRIL 30, 1947)	985
LAST 12 MONTHS RUNNING AVERAGE ON GUNS PRODUCED WITHIN ONE YEAR	. , 82