COPIES TO: C.K. DAVIS D.F. CARPENTER W.O. REISINGER B.E. STRADER F.J. CRAIG G.O. CLIFFORD M.R. WARDEN G.E. PINCKNEY A.L. FRENCH W.L. CLAY W.F.H. MATTLAGE BRIDGEPORT.	H.K. FAULKNER W.H. DAVIS H.A. BROWN R.H. GRACE H.J. HACKMAN (6) D.S. FOOTE D.E. MILLER S.W. ROSE R.A. WILLIAMSON A.J. BROWN R.E. WRIGHT
TOTAL JUSTIFIED COMPLAINTS	
MAY 1948	313
MAY 1947	83
TO DATE 1948	1346
TO DATE 1947	653
FOR 12 MONTHS ENDING MAY 31, 1948	2291
FOR 12 MONTHS ENDING MAY 31, 1947	1225
LAST 12 MONTHS RUNNING AVERAGE	191
LAST 12 MONTHS RUNNING AVERAGE (1 YEAR AGO)	102
LAST 12 MONTHS RUNNING AVERAGE (6 MONTHS AGO)	133
COMPLAINTS ON GUNS PRODUCED WITHIN ONE YEAR	•
CURRENT MONTH MAY 1948	268
DECEMBER 1947	133
MAY 1947	79
MAY 1946	O .
FOR 12 MONTHS ENDING MAY 31, 1948	1823
LAST 12 MONTHS RUNNING AVERAGE ON GUNS PRODUCED WITHIN ONE YEAR.	152

COMPLAINTS ON FIREARMS FOR MONTH ENDED MAY 31, 1948

MODEL 94	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 81 # JACKET HEAD LOOSE	1	3
O FAILS TO EJECT O MAGAZINE SIDE SPRING OUT OF ADJUSTMENT	1	1
O STEMS CHAMBER O MAGAZINE SPRING BROKEN	1	1
X NOT ACCURATE BOLT CARRIER BROKEN	1	1
X ROUGH CHAMBER	1 2	i
MISFIRES		1
BARREL LOCK SPRING AND MAGAZINE BROKEN	7	74
SPORTSMAN - 12 GA. O SHELLS STEM CHAMBER THREADS ON TAKE DOWN SCREW STRIPPED		1
FORE-END SPLIT MAGAZINE BROKEN AT FORE-END	1	1
BARREL MARRED	$\frac{1}{2}$	
SPORTSMAN - 16 GA. EXTRACTOR BROKEN X RECEIVER CUSHION LOOSE X EXTENSION LOOSE IN RECEIVER	1 2	1 1 1 3
MODEL 11 - 12 GA. O FAILS TO EJECT	1	1
BAD FINISH ON BARREL FAILS TO FEED	1	1
DEFECTIVE STOCK AND FORE-END	<u> 1 </u>	-1-
MODEL 11 - 16 GA. O SHELLS STEMS CHAMBER X TRIGGER AND SAFETY BINDS	1	2 1 3
MODEL 11 - 20 GA. O FAILS TO FEED		1

•	Z		=	
		PRODUCED	WITHIN YEAR	TOTAL
MODE	L 121	OIAE	TEAR	TOTAL
	FIRING PIN BROKEN		3	Ą
X	FIRING PIN STRIKES INSIDE RIM		. 5	6
0	STEMS CHAMBER BARREL LOOSE ON RECEIVER		7	7
ŏ	FAILS TO EJECT		1	1
X	ACTION BAR MACHINED WRONG		i	,
	ACTION BAR BROKEN		i	i
_	FORE-END SPLIT		1	1
O X	STEMS RETAINER	1.001	.1	2
X	CARTRIDGE WAY IN BREECH BLOCK OUT OF POSIT JAMS (SHELLS CATCH BY CARTRIDGE STOP)	ION	1	1
ô	BLOCK UNEVEN AT FACE		i	i
			23	27
MODE	. 4).4			
MUDE	L 141 FAILS TO EJECT		1	2
ŏ	SEAR AND SEAR LOCK OUT OF ADJUSTMENT		ż	4
Ŏ	SEAR AND TRIGGER OUT OF ADJUSTMENT		ī	Ť
0	SHELLS STEMS CHAMBER	•	1	1
Õ	JARS OFF.			1
X. 0	FIRING PIN STRIKES OFF CENTER SAFETY OUT OF ADJUSTMENT		1	1
•	CARTRIDGE STOP BROKEN		i	ż
	EXTRACTOR BROKEN			. 1
0	SHELLS FEED HARD UNDER EXTRACTION			Ş
Õ.	ACTION BINDS		1	1
X	MAGAZINE LOOSE (THREADS STRIPPED) STOCK SPLIT		i	i
X	EXTRACTOR NOT TO GAUGE (POORLY GROUND)		•	1
	CARTRIDGE STOP CHIPPED		1	1
			10	20
MODE	L 241			
0	FAILS TO DISCONNECT		2	2
X	POOR NOTCH ON FIRING PIN		3	3 ·
X	BARREL LOCK DOES NOT QUALIFY		1	12
Ô	FAILS TO EJECT		12	12
X O	SIGHTS OUT OF LINE TAKE DOWN LOOSE		র	5 4
X	FRONT SIGHT SLOT MILLED WRONG		1	1
••	STOCK CHECKED		1	1
X	JAMS (POOR CLAW ON EXTRACTOR)		1	1
	HAS M/141 ROLLED ON RECEIVER		2	5
X	CARTRIDGE GUIDE OUT OF POSITION SHELLS CATCH ON CARTRIDGE STOP		ī	1
O	FAILS TO COCK		i	1
•	inter is seen.		73	35

SHEET NO. 3

MODE X X	BARREL POORLY POLISHED BARREL LOOSE (SIDE PLAY IN BUSHING) STOCK BROKEN BARREL BENT STOCK MARRED	PRODUCED WITHIN ONE YEAR 1 1 1 1 1 1 1 1 1 8	TOTAL 1 1 1 1 1 1 1 1 8
MODE X	IL 31 - 16 GA. STOCK CHECKED TRIGGER PULLS WITH SAFE ON	2	2 1 3
MODE	STOCK BROKEN		1
MODE X X	TRIGGER PULL NOT PROPERLY ADJUSTED FAILS TO COCK FRONT SIGHT CROOKED	1 2 1	1 2 1
MODE O O X O X	FAILS TO EJECT FAILS TO EXTRACT EJECTOR TOO LOW SAFE OUT OF ADJUSTMENT BOLT CLOSES HARD SEAR STUD TOO SMALL	1 2 1 1	2211
MODE N N X O	NOT ACCURATE FAILS TO EJECT BARREL NOT STRAIGHT BOLT HANDLE LOOSE BURRS IN BARREL	1 2 1 1 1	1 3 1
MODE O O	CARTRIDGE RETAINER OUT OF ADJUSTMENT FAILS TO FEED EJECTOR TOO LOW (FAILS TO EJECT) BOLT BROKEN STOCK CHECKED FAILS TO EJECT BOLT PULLS OUT	10 1 1 1 18	13 1 2 1 1 2 20
**	JAMS FIRING PIN CAM PIN BROKEN FRONT SIGHT DAMAGED	1 - 1 - 34 -	1 1 43

SHEET NO A

•	•••		
		PRODUCED WITHIN	7074
MODE	L 513	ONE YEAR	TOTAL
X	FIRING PIN BLOW INSIDE RIM		1
X	KEY HOLES	14	14
X	BOLT HANDLE HITS TOP OF RECEIVER	i	1
	BOLT HANDLE BROKEN		1
X	BARREL PITTED	_ 2	2
		17	19
140051	e e la		
MOULI	514 2010000 0000		
	TRIGGER BENT		-
	• •	·	•
MODEL	521		
	FIRING PIN CAM PIN BROKEN	1	1
X	BAD SPOT IN BLUEING	i	1
X	NOT ACCURATE	4	4
	SEAR AND BOLT BROKEN	1	1
	STOCK MARRED	_1_	_1_
		8	8
MODE	. 550-1		:
O	EXTRACTOR OUT OF ADJUSTMENT	1	1
ŏ.	FAILS TO FEED	ż	ż
X	NOT ACCURATE	<u> </u>	3
X	JAMS (INSERT ROUGH)	7	. 7
0	FAILS TO EJECT	20	20
_	RECOIL CHAMBER SPLIT	<u>1</u>	1
0	FAILS TO CONNECT	9	9
0	FAILS TO EXTRACT	· I	} }a
0	NO CHAMFER ON FRONT END OF RECOIL CHAMBER MISFIRES	4	4
U	DEFECTIVE RECOIL CHAMBER	7	'
X	TAKE DOWN SCREW BUSHING LOOSE	j	4
^	OUTER MAGAZINE LOOSE IN INSERT	1	1
•	DISCONNECTOR SPRING WEAK	1	i
X	BOLT BINDS	1	1
X	CONNECTOR PIN OUT OF POSITION	1	1
	STOCK SPLIT AT TIP	1	1
	THREADS IN MAGAZINE RING IN BARREL POOR	- <u></u>	- <u>L</u>
		04	04
MODE	L 721		
#	STOCK CRACKED AT GRIP	27 .	28
ō	FAILS TO EJECT	j	1
X	BOLT CLOSES HARD	Ş	2
	FIRING PIN HOLE TOO MUCH CHAMFER	1	7
	BARREL ROLLED 399 SAVAGE]	7
	BOLT DAMAGED	i 1	1
	DEFECTIVE BOLT	211	-3K
		דר	3.7

SHEET NO. 5

MODEL 722 STOCK SPLIT SIDE OF TIP

CORRECTED IN RECENT PRODUCTION OVERSIGHT IN INSPECTION

CLOSE ADJUSTMENT NOT SHOWING UP IN FACTORY TEST RESULTING IN MALFUNCTION THROUGH USAGE. NOT COVERED BY INSPECTION.

COMPLAINTS RECEIVED DURING MAY 1948 - ON GUNS PRODUCED IN R THE FOLLOWING YEARS.

MODEL	1948	1947	1946	1945	MISC.& PARTS.
MODEL 81 SPORTSMAN - 12 GA. SPORTSMAN - 16 GA. SPORTSMAN - 20 GA.	1	7	7		
MODEL 11 - 12 GA: MODEL 11 - 16 GA: MODEL 11 - 20 GA.	2	2	2		
MODEL 121 MODEL 141 MODEL 241	12 2 17	11 8 16	10 2	,	
MODEL 31 - 12 GA. MODEL 31 - 16 GA. MODEL 31 - 20 GA.	5	3	1 1		
MODEL 37 MODEL 510 MODEL 511	254	5 5	1		
MODEL 512 MODEL 513 MODEL 514	15 1	19 16	5		
MODEL 521 MODEL 550-1 MODEL 721 MODEL 722	39 26 1	8 25 8	1		·