

Model 722 .257 calDate 6/11ZollerItem # 33647

GILLER															
No.	Rounds Fired	Malfunctions										Remarks			
		Firing	Unlocking	Primary Extraction	Secondary Extraction	Ejection	Cocking	Feeding	Loading	Locking	Breakages	Repairs	Gun Failures	Adjustments	
	0 - 20	OK													with K1701C
	21 - 40							11	-						Bolt overrides last Rd SS
	41 - 60							1	-						fast bolt overriding causing stem change last rd
	61 - 80							1	-						S
	81 - 100							11							SS SS 11
	101 - 120							11							SS
	121 - 140							111							SSS
	141 - 160							1							F
	161 - 180							11							BOLR (By pulling bolt back slow)
	181 - 200							1							Bolt overrides most every time on all 3 guns