COPIES TO: C.K. DAVIS D.E. CARPENTER W.O. REISINGER B.E. STRADER F.K. CRAIG G.O. CLIFFORD M.R. WARDEN G.E. PINCKNEY A.L. FRENCH W.L. CLAY W.F.H. MATTLAGE BRIDGEPORT.	H.K. FAULKNER W.H. DAVIS H.A. BROWN R.H. GRACE H.J. HACKMAN (6) D.S. FOOTE D.E. MILLER S.W. ROSE R.A. WILLIAMSON A.J. BROWN R.E. WRIGHT
TOTAL JUSTIFIED COMPLAINTS	• •
AUGUST 1948	96
AUGUST 1947	81
TO DATE 1948	1872
TO DATE 1947	990
* * * *	
FOR 12 MONTHS ENDING AUGUST 31, 1948	2380
FOR 12 MONTHS ENDING AUGUST 31, 1947	1366 ·
LAST 12 MONTHS RUNNING AVERAGE	198
LAST 12 MONTHS RUNNING AVERAGE (1 YEAR AGO)	113
LAST 12 MONTHS RUNNING AVERAGE (6 MONTHS AGO)	169
	• .
COMPLAINTS ON GUNS PRODUCED WITHIN ONE YEAR	• •
CURRENT MONTH AUGUST 1948	86
MARCH 1948	171
AUGUST 1947	66
AUGUST 1946	0
	· .
FOR 12 MONTHS ENDING AUGUST 31, 1948	2003
LAST 12 MONTHS RUNNING AVERAGE ON GUNS PRODUCED WITHIN ONE YEAR.	166

COMPLAINTS ON FIREARMS FOR MONTH ENDED AUGUST 31, 1948.

÷	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 81 # JACKET HEAD LOOSE O FAILS TO EJECT O MAGAZINE SIDE SPRING OUT OF ADJUSTMENT X NOT ACCURATE TAKE DOWN SCREW BINDS	1 1 2 1 1	2 1 2 1 1 1
SPORTSMAN - 12 GA. MAIN SPRING BROKEN O TRIGGER BINDS FORE-END SPLIT O FAILS TO EJECT	1	1 1 1 1 1
SPORTSMAN - 16 GA. O TRIGGER BINDS		
MODEL 11 - 12 GA. O SHELLS STEM CHAMBER O FAILS TO EJECT	1	· 2 1 3
MODEL 11 - 20 GA. O SHELLS STEM CHAMBER X FRONT SIGHT BASE OUT OF POSITION	-1-	1 .
MODEL 121 FIRTNG PIN BROKEN O SHELLS STEM CHAMBER O TAKES MAX. PLUG O FAILS TO EJECT O FAILS TO FEED	1	1 2 1 1 1
MODEL 141 O SHELLS STEM CHAMBER CARTRIDGE STOP BROKEN X FIRING PIN HOLE OUT OF POSITION	2 2	2 2

MODEL 241	PRODUCED WITHIN ONE YEAR	TOTAL
O FAILS TO DISCONNECT X POOR NOTCH ON FIRING PIN O FAILS TO EJECT X SIGHTS OUT OF LINE X NOT ACCURATE (MUZZLE UPSET) O CARTRIDGE STOP OUT OF ADJUSTMENT X POOR BLUEING X JAMS (POOR CLAW ON EXTRACTOR) O SHELLS STEM CHAMBER DEFECTIVE BARREL O DISCONNECTOR DAMAGED O FAILS TO COCK RECEIVER CRACKED	1221	122111111121
MODEL 31 -12 GA. DEFECTIVE BARREL		1
MODEL 510 U FATES TO EXTRACT TAKE DOWN SCREW THREADS BAD IN RECEIVER	1 1 2	1 1 2
MODEL 512 U CARTRIDGE RETAINER OUT OF ADJUSTMENT O FAILS TO EJECT # BOLT PULLS OUT N NOT ACCURATE (SIGHTS OUT OF LINE)	3	3
MODEL 513 X KEY HOLES (POOR RIFLEING)	_6_	- 6
MODEL 514 X DEFECTIVE BOLT BOLT HANDLE BROKEN	1 2	1 1 2-
MODEL 521 X BOLT HANDLE LOOSE	1	1

SHEET NO. 3

	PRODUCED WITH ONE YEAR	
MODEL 550-1 X NOT ACCURATE X JAMS (INSERT ROUGH) O FAILS TO EJECT O FAILS TO CONNECT BROKEN EXTRACTOR FAILS TO OPERATE PROPERLY SHELLS STEM CHAMBER CONNECTOR SPRING WEAK X BOLT BINDS SHELLS SWELL DEFECTIVE BOLT POOR THREADS IN RECEIVER	1 2 2 1 1 1 2 2 1 1 1	1 2 2 1 1 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1
MODEL 721 # STOCK CRACKED AT GRIP O FAILS TO EJECT DEFECTIVE BOLT X BAD SPOT IN BARREL • EXTRACTOR LOOSE SEAR BINDS O TRIGGER PIN OUT OF POSITION	7 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7 2 2 1 1 1
MODEL 722 BOLT HANDLE CRACKED BOLT CRACKED X BARREL LOOSE IN RECEIVER	1 1 3	1 1 1 3

CORRECTED IN RECENT PRODUCTION
OVERSIGHT IN INSPECTION
CLOSE ADJUSTMENT NOT SHOWING UP IN
FACTORY TEST RESULTING IN MALFUNCTION THROUGH USASE NOT COVERED BY INSPECTION

COMPLAINTS RECEIVED DURING AUGUST 1948 - ON GUNS PRODUCED IN THE FOLLOWING YEARS.

MODEL	1948	1947	1946	1945	MISC. & PARTS
MODEL 81 SPORTSMAN - 12 GA.	1	5	1		
SPORTSMAN - 16 GA. SPORTSMAN - 20 GA. MODEL 11 - 12 GA.	1.		1 2		
MODEL 11 - 16 GA. MODEL 11 - 20 GA.	1	1.	1 .		3
MODEL 121 MODEL 141 MODEL 241	18	Š	•		
MODEL 31 - 12 GA. MODEL 31 - 16 GA. MODEL 31 - 20 GA.	•	•	. 1		
MODEL 37 MODEL 510		2	•		
MODEL 511 MODEL 512 MODEL 513	1	5			
MODEL 51 [‡] MODEL 521 MODEL 550-1	2 1 16				
MODEL 721 MODEL 722	i¥ 3	1			•

H.E.WEEKS:FH 9/8/48