

7-1-55

722

Aluminum Bil. indium & test,

320 P50

1

0

Rem 117 SF RM 1/0

80

120

Rem 100 P5F 1/60

400

240

Rem 117 SF 250

320

7/7/55

X HARD to EXTRACT FILM COILS

Rem 117 SF RM 360

RM 400

RM 440

RM 480

RM 500

1
1x
3
1
X

Cannot be re-gaged. Box enlarged too much.
Test stopped 7-7-55.

7-1-55

722
Aluminum

257 Robt.
alt. entrance
Tid.

335947

1

Rem 117 S.P. PM 40

" " 80

Rem 100 P.S.P. 120

" " 160

" " RM 200

" " RM 240

" " RM 280

" " RM 320

Rem 117 S.P. RM 360

" " RM 400

" " RM 440

" " PM 480

" " PM 500

X
X
X

OK

OK

OK

OK

OK

OK

OK

OK

OK
Hand to extract fired cases

Cannot be base-paged. Base enlarged too much.
Test stopped 7-7-55

7-1-55 722 257 Rbts 320/150
 Aluminum Rb. evidence Test

Rm 117 SR RM 43 SD

Rm 117 SR RM 120

" " " RM 160

" " " RM 180

Rm 100 SR RM 200

" " " RM 240

" " " RM 280

" " " RM 320

" " " RM 360

Rm 117 SR RM 400

" " " RM 440

" " " RM 480

" " " RM 520

7/7/55

Will be new plug.
 at router

Front cover, back cover

Cannot be fore-gaged. Bore enlarged too much.
 Test stopped 7-7-55