

cc: H.J. Hackman

Ilion, New York
March 14, 1956

R. A. WILLIAMSON (2)

MODELS 721-722 - QUALITY

It has been called to our attention that the edges around the filling cuts for the ejection and loading port opening are too sharp and present a source for injury to the shooter's hand. We investigated by checking several of our rifles and apparently find the complaint justified. We also made comparison with several competitive rifles and find that these corners are usually properly "broken" and smoothly rounded.

It is possible that this job is being properly filed in an earlier operation and then the corners are made sharp during a subsequent polishing operation.

SMA:T

S. M. Alvis, Manager
Ilion Research Division