

AMMUNITION		Shooter		No. of Rds.		MALFUNCTIONS												REMARKS									
PREVIOUS 3,600 RDS.		FG	3,650			Firing	Extraction	Don't Blow Back	Ejection	Locking Open	Feed from Mag.	Feed from Mag.	Double Feed From Magazine	Dropped Shell	Failed to Trip Carrier Latch	Stem Carrier	High	Low	Rt.	Stem Chamber	Locking Up	Loading	Breakages	Replacement	Gun Failure	Adjustments	
2ND REMINDER REM-220 SP		FG	3,650																								OK
" " "		FG	900																								OK
" " "		FG	750																								OK
" " "		FG	800																								OK
" " "		FG	950																								OK
" " "		FG	900																								OK
" " "		FG	950																								OK
" " "		FG	950																								OK
" " "		FG	400																								OK
" " "		FG	50																								OK
" " "		FG	100																								OK
" " "		FG	250																								OK
" " "		FG	300																								OK
" " "		FG	150																								OK
" " "		FG	300																								OK
" " "		FG	350																								OK
" " "		FG	400																								OK

DATE 3-20-57 MODEL 721 CAL. 44 30-06 GUN NO. 336942 Sheet No. 7
 DESCRIPTION OF TEST: QUALITY AND TEST
 Total Rds. Fired _____
 Total Malfunctions _____
 Rate _____