

47-6000
CML 232

Filet line

1-13-04

Gun Serial No.	Headspace		Ammunition	Rounds	No. Malf	Type of Malfunction	Trigger Pull (lbs.)			Accuracy (Inches) Center to Center								
	Go	No Go					Avg. of 10	Max.	Min.	Accuracy Device			Shoulder			5-Shot Group		
										1	2	3	Avg.	1	2	3	Avg.	
2815	OK	OK	Win. PSP. Rem. SP	20	4	2 Stem Right 2 Stem low	3.5	4.0	3.25	2.0	1.45	1.85	1.73	1.55	2.6	2.0	2.0	
2757	OK	OK	Win. PSP Rem. SP	20	0		6.98	9.25	5.0	3.2	2.5	2.0	2.56	1.5	2.15	1.95	1.86	
2880	OK	OK	Win. PSP Rem. SP	20	0		See Footnote 1			3.05	2.0	1.9	2.31	1.8	1.55	1.4	1.58	
3187	OK	OK	Win. PSP Rem. SP	20	0		5.43	5.75	5.0	2.72	2.2	2.85	2.59	2.0	1.4	2.15	1.85	
2825	OK	OK	Win. PSP Rem. SP	20	3	1 Stem low 2 Stem hi - left	7.65	9.5	5.0	4.1	1.9	2.55	2.85	3.0	1.6	1.6	2.06	
2759	Tight	OK	Win. PSP Rem. SP	20	0		4.0	4.5	3.75	3.6	4.1	1.8	3.16	3.1	2.8	1.85	2.58	
2863	OK	OK	Win. PSP Rem. SP	20	2	1 Stem hi - left 1 Stem right	3.25	4.5	2.75	1.75	1.6	2.5	1.95	1.85	1.35	2.5	1.9	
2845	OK	OK	Win. PSP Rem. SP	20	3	2 Stem hi - left 1 Stem hi - right	4.83	5.5	4.25	2.3	1.5	2.2	2.0	1.65	1.3	.5	1.15	
2769	OK	OK	Win. PSP Rem. SP	20	1	Tight under rail	5.53	6.25	4.75	4.7	2.42	2.65	3.25	.74	.75	2.3	1.26	
2821	OK	OK	Win. PSP Rem. SP	20	0		5.85	6.5	5.25	2.3	1.3	1.4	1.66	1.6	1.3	1.92	1.6	

1. Bolt Jammed. When disassembled, small piece of Nylon found to cause jam.