

40-000
 004-000
 Pilot Line

Gun Serial No.	Headspace		Ammu- nition	Rounds	No. Mal- function	Trigger Pull (lbs.)	Accuracy (Inches)										Center to Center	
							Accuracy Device					Shoulder						
	No						5-Shot		Avg.	5-Shot		Avg.	5-Shot		Avg.	5-Shot		Avg.
	Go	Go					1	2		3	1		2	3		1	2	
315	OK	OK	Win. PSP Rem. SP	20 4 20 0	Type of Malfunction 2 Stem Right 2 Stem low	Avg. of 10	Max. Min.	2.0	1.45	1.85	1.73	1.55	2.6	2.0	2.01			
2757	OK	OK	Win. PSP Rem. SP	20 0 20 0		6.98	9.25 5.0	3.2	2.5	2.0	2.56	1.5	2.15	1.95	1.86			
2880	OK	OK	Win. PSP Rem. SP	20 0 20 0		See Footnote 1		3.05	2.0	1.9	2.31	1.8	1.55	1.4	1.58			
3187	OK	OK	Win. PSP Rem. SP	20 0 20 0		5.43	5.75 5.0	2.72	2.2	2.85	2.59	2.0	1.4	2.15	1.85			
2825	OK	OK	Win. PSP Rem. SP	20 3 20 0	1 Stem low 2 Stem hi - left	7.65	9.5 5.0	4.1	1.9	2.55	2.85	3.0	1.6	1.6	2.06			
2759	Tight	OK	Win. PSP Rem. SP	20 0 20 0		4.0	4.5 3.75	3.6	4.1	1.8	3.16	3.1	2.8	1.85	2.58			
2863	OK	OK	Win. PSP Rem. SP	20 2 20 0	1 Stem hi - left 1 Stem right	3.25	4.5 2.75	1.75	1.6	2.5	1.95	1.85	1.35	2.5	1.9			
2845	OK	OK	Win. PSP Rem. SP	20 3 20 0	2 Stem hi - left 1 Stem hi - right	4.83	5.5 4.25	2.3	1.5	2.2	2.0	1.65	1.3	.5	1.15			
2769	OK	OK	Win. PSP Rem. SP	20 1 20 0	2 Stem right	5.53	6.25 4.75	4.7	2.42	2.65	3.25	.74	.75	2.3	1.26			
2821	OK	OK	Win. PSP Rem. SP	20 0 20 0	Tight under rail	5.85	6.5 5.25	2.3	1.3	1.4	1.66	1.6	1.3	1.92	1.6			

1. Bolt Jammed. When disassembled, small piece of Nylon found to cause jam.