

JOB TESTING + SHIPPINGNO. 5
PAGE 1 OF 1

DETAILS OF (PRESENT PROPOSED) METHOD	OPERATION	TRANSPORT	INSPECTION	DELAY	STORAGE	DISTANCE IN FEET	QUANTITY	TIME	ANALYSIS				NOTES	ACTION				
									WHAT?	WHERE?	WHEN?	HOW?		ELIMINATE	COMBINE	SEQUENCE	PLACE	DEFINITION
(1) <u>Wait</u> IN LOADING ROOM	☒	☒	☒	☒	☒									WHILE AMMO IS HAND LOADED				
(2) <u>Wipe out Barrel</u>	☒	☒	☒	☒	☒									CLEAN CLOTH. USE HOPKES IF NOT.				
<u>Take to Gallery</u>	☒	☒	☒	☒	☒									26-3 HOPKES				
<u>Wait</u>	☒	☒	☒	☒	☒									ONLY WHEN IN USE				
<u>PROOF TEST</u>	☒	☒	☒	☒	☒									REM FROM VIDE.				
<u>STAN. BARREL POINT FOUR B.S.I.</u>	☒	☒	☒	☒	☒													
<u>TAKE TO 150 YD RANGE</u>	☒	☒	☒	☒	☒													
(1) <u>A.T.</u>	☒	☒	☒	☒	☒									JUST AFTER NOON				
<u>BORISIGHT RIFLE AND FACTORY AMMO</u>	☒	☒	☒	☒	☒									SHOOT STANDING POSITION				
<u>TEST 3-5 SHOTS AROUND RANGE</u>	☒	☒	☒	☒	☒									NOTE IN SEQUENCE SHOT IF RIFLE SHOT.				
<u>PICK UP TARGETS</u>	☒	☒	☒	☒	☒									DOWN RANGE, FOR REMOVAL				
<u>RETURN TO CUSTOMER</u>	☒	☒	☒	☒	☒													
<u>WIPE WITH HOPKES</u>	☒	☒	☒	☒	☒									SHOOTING FINE LINE.				
<u>WIPE OUT BARREL</u>	☒	☒	☒	☒	☒									CLEANING OIL F.A.M.				
<u>WIPE OFF RIFLE</u>	☒	☒	☒	☒	☒									HOPKES				
<u>POLISH END OF BOLT FORM</u>	☒	☒	☒	☒	☒									3-36 OIL.				
<u>PICK UP SHIPPING TICKET</u>	☒	☒	☒	☒	☒									WITH BRUSH ON BOLT REMOVED				
<u>DELIVER TO SHIPPING</u>	☒	☒	☒	☒	☒									SHIPPING TICKET TARGET				
	☒	☒	☒	☒	☒									WARD FENTON				
	☒	☒	☒	☒	☒									DEPT. OF THE ARMY				
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													
	☒	☒	☒	☒	☒													